



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Black
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-17
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-27
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	45
Total items failed	29

MOT #25	2024-03-14 17:09
MOT test number	839445507843
Result	✓ Passed
Next expiry date	2025-03-27
Minor	Windscreen damaged but not adversely affecting driver's view Stonechip outside of swept area (3.2 (a) (i))

MOT #24	2024-03-13 11:57
MOT test number	594990252344
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view Stonechip outside of swept area (3.2 (a) (i))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #23	2023-03-28 14:44
MOT test number	862156154949
Result	✓ Passed

MOT #22	2022-03-25 15:54
MOT test number	142785667958
Result	✓ Passed

**MOT #21** 2022-03-14 16:34**MOT test number** 716981616399**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #20** 2021-01-11 16:31**MOT test number** 379080604704**Result** ✓ Passed**MOT #19** 2021-01-07 07:02**MOT test number** 817013141381**Result** ✗ Failed**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Bumper insecure (6.1.4 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #18** 2020-01-15 12:19**MOT test number** 778379684498**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17** 2020-01-15 12:19**MOT test number** 585077388915**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #16** 2019-01-28 12:06**MOT test number** 997993302955**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2019-01-28 12:06**MOT test number** 711841539096**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2018-01-29 11:54**MOT test number** 664878635973**Result** ✓ Passed**MOT #13** 2017-01-25 15:31**MOT test number** 122805246497**Result** ✓ Passed**Advice** Rear bumper damaged**Advice** Oil leak

**MOT #12** 2017-01-25 10:21**MOT test number** 790685719727**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Rear bumper damaged**Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Advice** Oil leak**MOT #11** 2016-02-01 12:08**MOT test number** 486990795980**Result** ✓ Passed**MOT #10** 2016-02-01 08:27**MOT test number** 911557562346**Result** ✗ Failed**Fail** Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Direction indicator incorrect colour white (1.4.A.2f)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Direction indicator incorrect colour white (1.4.A.2f)**MOT #9** 2015-02-02 12:56**MOT test number** 919733935074**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8** 2014-02-06 09:47**MOT test number** 887897034039**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside rear tyre sidewalls perished/cracking-recommend tracking.

MOT #7 2013-02-05 09:21**MOT test number** 369606833062**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Front number plate damaged/both rear tyres cracking

MOT #6 2013-02-05 09:21**MOT test number** 797896133027**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Notice** Front number plate damaged/both rear tyres cracking
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #5 2012-02-29 08:55**MOT test number** 977200362093**Result** ✓ Passed

**MOT #4** 2012-02-27 09:27**MOT test number** 896778552096**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Centre Stop lamp not working (1.2.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2011-03-10 10:11**MOT test number** 765639061072**Result** ✓ Passed

- Notice** Centre stop light inoperative.
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2 2010-03-19 10:03**MOT test number** 142678270476**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Off side front tyre worn low on inner edge
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #12010-03-19 10:03

MOT test number150258070479

ResultX Failed

AdviceFront Brake pad(s) wearing thin (3.5.1g)

Pass with rectificationFront Headlamp aim too high (1.8)

AdviceFront brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

AdviceExhaust has part of the system slightly deteriorated (7.1.1a)

NoticeOff side front tyre worn low on inner edge

Pass with rectificationFront Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-03-28
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-03-28	16 mi
Registration #2	2010-03-19	21.455 mi
Registration #3	2011-03-10	27.672 mi
Registration #4	2012-02-27	34.109 mi
Registration #5	2012-02-29	34.156 mi
Registration #6	2013-02-05	40.619 mi
Registration #7	2014-02-06	47.088 mi
Registration #8	2015-02-02	52.728 mi
Registration #9	2016-02-01	58.170 mi
Registration #10	2016-02-01	58.170 mi
Registration #11	2017-01-25	62.360 mi
Registration #12	2017-01-25	62.360 mi
Registration #13	2018-01-29	67.422 mi
Registration #14	2019-01-29	72.484 mi
Registration #15	2019-01-29	72.484 mi
Registration #16	2019-01-29	72.484 mi
Registration #17	2019-01-29	72.484 mi
Registration #18	2019-01-29	72.484 mi
Registration #19	2019-01-29	72.484 mi
Registration #20	2019-01-29	72.484 mi
Registration #21	2019-01-29	72.484 mi
Registration #22	2019-01-29	72.484 mi
Registration #23	2019-01-29	72.484 mi
Registration #24	2019-01-29	72.484 mi
Registration #25	2019-01-29	72.484 mi



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

G4EE7705908