





report date: 2024-03-29

General information

Make	BMW
Model	640 530D M SPORT TOURING
Colour	Grey
Year of manufacture	2013
Top speed	155 mph
0 - 60 mph	5.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	540 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



MOT history	
MOT expiry date	2024-08-21
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	4
Total items failed	5
MOT #13	2023-08-22 17:00
MOT test number	501515698958
Result	✓ Passed
Next expiry date	2024-08-21
MOT #12	2022-04-29 10:20
MOT test number	207568716114
Result	✓ Passed
MOT #11	2020-11-25 09:21
MOT test number	200580281336
Result	✓ Passed
MOT #10	2020-08-13 13:03
MOT test number	592912565101
Result	✓ Passed
MOT #9	2020-08-12 09:56
MOT test number	411327549433
Result	× Failed
Fail Nearside Rear Tyre has a bulge, caused by separation	or partial failure of its structure (5.2.3 (d) (ii))
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	

CarCheck.co.uk page 2/11



YT63DXC

report date: 2024-03-29

MOT #8	2019-09-04 10:01
MOT test number	464500531172
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

Advice Nearside Rear Nail in tyre	
MOT #7	2018-09-21 15:41
MOT test number	734529737852
Result	✓ Passed
MOT #6	2018-08-25 14:37
MOT test number	236018347619
Result	✓ Passed
MOT #5	2018-08-23 14:35
MOT test number	786839140501
Result	✓ Passed
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #	‡4	2018-08-23 09:26
MOT t	est number	880646432472
Result	t	X Failed
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure	of its structure (5.2.3 (d) (i))

MOT #3	2017-08-10 08:33
MOT test number	276483496205
Result	✓ Passed


CarCheck.co.uk page 3/11



YT63DXC

report date: 2024-03-29





CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

Plate changes	More info >
See in this check if this BMW had different number plates.	
Number of plates	
Correct registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-03
Last registration	2023-08-22
Complete history	See info



Registration #1	2013-09-03	16 mi
Registration #2	2016-08-12	23.485 mi
Registration #3	2017-08-09	26.590 mi
Registration #4	2017-08-10	26.590 mi
Registration #5	2018-08-23	30.295 mi
Registration #6	2018-08-23	30.296 mi
Registration #7	2018-08-25	30.335 mi
Registration #8		71.777 es
Registration #9		71.777 es
Registration #10		77,777 44
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
60295	
60482	
60501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1488 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1820 kg
Max. allowed weight	2470 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 33608678