



AE58BZL

report date: 2024-03-28

General information

Make	AUDI
Model	A8 TDI QUATTRO SPORT
Colour	Grey
Year of manufacture	2008
Top speed	151 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	450 Nm at 3.250 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	32.1 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-07-27
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-26
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-08-01
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	26
Total items failed	3

MOT #16 2023-07-18 14:43**MOT test number** 595388198307**Result** ✓ Passed**Next expiry date** 2024-08-01

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement marked with yellow chalk both top arms (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view chip crack (3.2 (a) (i))

MOT #15 2022-07-22 11:49**MOT test number** 965991420717**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2021-08-02 15:12**MOT test number** 973438967622**Result** ✓ Passed

**MOT #13** 2021-08-02 15:12**MOT test number** 414338193499**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2021-01-21 16:19**MOT test number** 915707928464**Result** ✓ Passed**MOT #11** 2019-07-23 13:44**MOT test number** 779158825291**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge. (5.2.3 (e))**MOT #10** 2018-09-05 15:06**MOT test number** 570864351924**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2018-09-05 10:53**MOT test number** 525514712530**Result** ✗ Failed**MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Exhaust system insecure (6.1.2 (a))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2017-09-06 14:11**MOT test number** 480516660217**Result** ✓ Passed**MOT #7** 2016-09-15 10:31**MOT test number** 981365554123**Result** ✓ Passed**MOT #6** 2015-09-12 10:50**MOT test number** 127836409471**Result** ✓ Passed**MOT #5** 2014-09-12 11:13**MOT test number** 257255554266**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-09-11 12:23**MOT test number** 569884354271**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-09-24 12:05
MOT test number	689087463270
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2012-09-21 14:12
MOT test number	737385462207
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2011-09-28 14:18
MOT test number	949291371290
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-30
Last registration	2023-07-18
Complete history	See info



Registration #1	2008-09-30	6 mi
Registration #2	2011-09-28	26.292 mi
Registration #3	2012-09-21	38.273 mi
Registration #4	2013-09-24	49.957 mi
Registration #5	2014-09-11	60.598 mi
Registration #6	2014-09-12	60.604 mi
Registration #7	2015-09-12	70.229 mi
Registration #8	2016-09-15	78.002 mi
Registration #9	2017-09-06	85.275 mi
Registration #10	2018-09-05	92.385 mi
Registration #11	2019-09-05	99.495 mi
Registration #12	2020-09-05	106.605 mi
Registration #13	2021-09-05	113.715 mi
Registration #14	2022-09-05	120.825 mi
Registration #15	2023-07-18	127.935 mi
Registration #16	2023-07-18	127.935 mi
Registration #17	2023-07-18	127.935 mi
Registration #18	2023-07-18	127.935 mi
Registration #19	2023-07-18	127.935 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2028 mm
Height	1455 mm
Length	5181 mm
Wheel base	3074 mm
Kerb weight	1740 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	ASB 090101