





report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET POP STAR
Colour	White
Year of manufacture	2014
Top speed	102 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date	2021-09-28
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/14



WM63ULC report date: 2024-03-29

MOT history

MOT expiry date	2024-09-30
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	29
Total items failed	13

MOT #14	2023-09-29 13:55
MOT test number	530659642408
Result	✓ Passed
Next expiry date	2024-09-30
Advice Rear Brake disc worn, pitted or scored, but not seriously was advice Front Brake disc worn, pitted or scored, but not seriously (1.1.14 (a) (ii))	

MOT #13	2023-09-26 11:58
MOT test number	178017887599
Result	× Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened heaven (1.1.14 (a) (ii))	vily worn on inner faces
Fail Rear Lower Engine mounting bracket damaged or deteriorated resulting in 6 (6.1.8 (a) (i))	excessive movement
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.)	14 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

MOT #11 2022-09-26 09:15 **MOT** test number 732680759223 Result **X** Failed Offside Front Inner Tyre has ply or cords exposed 2055516 (5.2.3 (d) (ii)) Fail Central Seat belt pretensioner missing where fitted as original equipment (7.1.4 (a)) Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail **Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b)) **Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #10	2021-10-01 14:23
MOT test number	860668218836
Result	✓ Passed
MOT #9	2021-09-29 13:08
MOT test number	286162165830
Result	X Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Sesult

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #6

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice Items removed from driver's view prior to test

Advice Child Seat fitted not allowing full inspection of adult belt x2 in rear off car

Advice Have front wheel alignment checked

CarCheck.co.uk page 5/14



Fail

WM63ULC

report date: 2024-03-29

2019-01-14 09:38 **MOT #4** 505891283258 **MOT** test number Result × Failed Fail Windscreen washer not working (3.5 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e)) **Advice** Items removed from driver's view prior to test Advice Have front wheel alignment checked Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Headlamp not working on dipped beam both (4.1.1 (a) (ii)) **Advice** Child Seat fitted not allowing full inspection of adult belt x2 in rear off car **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge on limit very close to cords (5.2.3 (e))

MOT #3		2018-01-19 13:02
MOT test	number	368155369653
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	


Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2	2017-01-19 09:48
MOT test number	597190571923
Result	✓ Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Front Tyre worn close to the legal limit Both (4.1.E.1)	

CarCheck.co.uk page 6/14



report date: 2024-03-29



CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Expires: 30 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	30 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-01-23
Last registration	2023-09-29
Complete history	See info



Registration #1	2014-01-23	23 mi
Registration #2	2017-01-19	31.188 mi
Registration #3	2017-01-19	31.188 mi
Registration #4	2018-01-19	35.622 mi
Registration #5	2019-01-14	41.231 mi
Registration #6	2019-01-14	41.232 mi
Registration #7	2020-01-03	47.995 mi
Registration #8	2021-01-21	53.111 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1784 mm
Height	1667 mm
Length	4352 mm
Kerb weight	1315 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number CarCheck.co.uk	5377220 page 14/14