



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA ACTIVE ECO
Colour	White
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	119 g/km
CO2 label	C





## MOT history

MOT expiry date	2021-09-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	44
Total items failed	2

MOT #12 2020-09-18 09:56

MOT test number 387048217220

Result ✓ Passed

Next expiry date 2021-09-17

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases rear joint (6.1.2 (a))

MOT #11 2020-09-17 10:21

MOT test number 659404444831

Result ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases rear joint (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2019-09-16 14:36**MOT test number** 921766711369**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2019-09-16 10:41**MOT test number** 409884153327**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #8** 2018-09-17 14:18**MOT test number** 285289338905**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front shocker casing corroded**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #7**

2018-09-17 12:50

**MOT test number**

878553110015

**Result****✗ Failed**

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Offside Front shocker casing corroded

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #6**

2017-09-15 12:12

**MOT test number**

763357413807

**Result****✓ Passed**

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear coil spring corroded both (2.4.C.1b)

**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

**MOT #5** 2017-09-15 07:52**MOT test number** 895600749033**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear coil spring corroded both (2.4.C.1b)
- Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Fail** Driver's door cannot be opened from inside the vehicle (6.2.B.1b)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2016-08-31 07:44**MOT test number** 608665510764**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #3** 2015-09-16 12:11**MOT test number** 765364589955**Result** ✓ Passed**MOT #2** 2014-08-06 10:18**MOT test number** 369078214299**Result** ✓ Passed

- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)



MOT #1	2013-08-07 11:32
MOT test number	395209913225
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-08-26
Last registration	2020-09-18
Complete history	<a href="#">See info</a>



Registration #1	2010-08-26	22 mi
Registration #2	2013-08-07	29.312 mi
Registration #3	2014-08-06	35.266 mi
Registration #4	2015-09-16	38.842 mi
Registration #5	2016-08-31	42.379 mi
Registration #6	2017-09-15	45.735 mi
Registration #7	2017-09-15	45.735 mi
Registration #8	2019-09-18	55.277 mi
Registration #9	2019-09-18	55.277 mi
Registration #10	2019-09-18	55.277 mi
Registration #11	2019-09-18	55.277 mi
Registration #12	2019-09-18	55.277 mi
Registration #13	2019-09-18	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5718881