



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Silver
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-08
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-12
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	40
Total items failed	9

MOT #17	2023-10-31 12:47
MOT test number	186033871629
Result	✓ Passed
Next expiry date	2024-11-12
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2023-10-26 15:33

MOT test number

950653211644

Result**✗ Failed**

- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #15

2022-11-03 18:51

MOT test number

864157551578

Result**✓ Passed**

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

**MOT #14**

2021-11-05 16:23

MOT test number

781641695560

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front wipers split/smearing
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2021-11-05 16:23

MOT test number

550628588638

Result

✗ Failed

- Advice** Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Front wipers split/smearing

MOT #12

2020-11-04 16:52

MOT test number

284434276503

Result

✓ Passed

**MOT #11** 2019-11-07 11:37**MOT test number** 240525103365**Result** ✓ Passed**MOT #10** 2018-11-01 18:22**MOT test number** 618092248505**Result** ✓ Passed**MOT #9** 2017-10-31 09:36**MOT test number** 480423453216**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**MOT #8** 2017-10-25 10:57**MOT test number** 830272111829**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-11-10 10:52**MOT test number** 106693463192**Result** ✓ Passed

**MOT #6** 2016-11-08 10:06**MOT test number** 124669197344**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin INNER PAD (3.5.1g)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2015-10-30 13:36**MOT test number** 164445264075**Result** ✓ Passed**MOT #4** 2014-11-07 10:24**MOT test number** 429221614414**Result** ✓ Passed**MOT #3** 2013-11-05 09:50**MOT test number** 285559203355**Result** ✓ Passed



MOT #2 2012-11-10 10:16

MOT test number 545365712398

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Rear brake balance high on RBT
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #1 2011-10-14 12:11

MOT test number 465897481208

Result ✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** Nail in offside rear tyre



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 WN58YTJ
Plate since	2024-03-28
Current registration	 WN58YTJ
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-12
Last registration	2023-10-31
Complete history	See info



Registration #1	2008-11-12	24 mi
Registration #2	2011-10-14	9.545 mi
Registration #3	2012-11-10	14.201 mi
Registration #4	2013-11-05	19.439 mi
Registration #5	2014-11-07	24.313 mi
Registration #6	2015-10-30	28.960 mi
Registration #7	2016-11-08	32.804 mi
Registration #8	2016-11-10	32.813 mi
Registration #9	2017-10-25	37.479 mi
Registration #10	2017-10-31	37.489 mi
Registration #11	2018-10-31	37.489 mi
Registration #12	2019-10-31	37.489 mi
Registration #13	2020-10-31	37.489 mi
Registration #14	2021-10-31	37.489 mi
Registration #15	2022-10-31	37.489 mi
Registration #16	2023-10-31	37.489 mi
Registration #17	2023-10-31	37.489 mi
Registration #18	2023-10-31	37.489 mi
Registration #19	2023-10-31	37.489 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1078130