






report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	White
Year of manufacture	2012
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	58.9 mpg
Consumption combined	55.4 mpg



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-07-07

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-30
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	29
Total items failed	1

MOT #12	2023-07-01 09:21
MOT test number	112541007768
Result	✓ Passed
Next expiry date	2024-06-30
Advice Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))	

MOT #11	2023-06-30 11:46
MOT test number	993945415809
Result	× Failed
MAJOR Nearside Front Suspension arm pin or bush excessively worn rear arm bush (5.3.4 (a) (i)) Advice Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))	

MOT #10	2022 05 12 00.21
MOI #10	2022-05-13 08:21
MOT test number	431272464287
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.81mm (5.2.3 (e))	

MOT #9	2021-05-08 09:48
MOT test number	237400558217
Result	✓ Passed

CarCheck.co.uk page 3/13



GU12NTD

report date: 2024-03-29

MOT #8		2020-07-17 09:24
MOT test	number	498708510552
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #7		2019-05-15 16:02
MOT test	number	546018884057
Result		✓ Passed
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Under body corrosion (inner body seals)	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Under tray fitted	
Minor	Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))	
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Front steering column upper universal joint slight play	

CarCheck.co.uk page 4/13



Result

GU12NTD report date: 2024-03-29

× Failed

MOT #6 2019-05-15 15:10

MOT test number 532333061701

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front steering column upper universal joint slight play

Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Under body corrosion (inner body seals)

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Under tray fitted

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords marked (5.2.3 (d) (i))

Minor Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))

MOT #5 2018-05-01 09:42

MOT test number 750368543160

Result
✓ Passed

MOT #4 2017-05-04 15:31

MOT test number 600547002345

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 5/13



Advice

GU12NTD report date: 2024-03-29

MOT test number
983014783654

Result
Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Front registration plate missing (6.3.1a)

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2016-03-16 09:09 **MOT test number** 373998949098 Result ✓ Passed **MOT #1** 2015-03-03 09:06 **MOT** test number 137842465431 Result Passed Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



GU12NTD

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK AN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-08
Last registration	2023-07-01
Complete history	See info



Registration #1	2012-03-08	23 mi
Registration #2	2015-03-03	45.423 mi
Registration #3	2016-03-16	58.804 mi
Registration #4	2017-05-04	71.236 mi
Registration #5	2017-05-04	71.236 mi
Registration #6	2018-05-01	81.669 mi
Registration #7	2019-05-15	93.925 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	2011 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1261 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2
Engine number	K9K-020445

CarCheck.co.uk page 13/13