





report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 R-DESIGN LUX NAV
Colour	Bronze
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-09
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #7		2024-02-06 09:27
MOT test n	umber	794852126970
Result		✓ Passed
Next expir	y date	2025-02-09
Advice Nearside Rear Lower Child Seat fitted not allowing full inspection of adult belt		belt
Advice Central Front Brake disc worn, but not excessively both front brake discs lipped on inner and outer faces (1.1.14 (a) (i))		
Advice Offside Front Inner Brake pad(s) wearing thin inner pad getting low (1.1.13 (a) (ii))		
Advice Central Rear Upper Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both rear drop link bushes (5.3.4 (a) (i))		

MOT #6	2023-02-01 09:43
MOT test number	313075726189
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge tyre wo (e))	orn on inner edge (5.2.3
Advice Central Rear Upper Anti-roll bar pin or bush worn but not resulting in excrear bushes slight cracking (5.3.4 (a) (i))	cessive movement both
Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking	g in treads (5.2.3 (d) (ii))
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge tyre worn depth 2.8mm close to limit (5.2.3 (e))	n on inner edge tread
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking in	n treads (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



FE65KXS

report date: 2024-03-28

MOT #5 2022-01-25 11:05

MOT test number 841778436512

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 235/60/18 (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2021-02-10 14:54

MOT test number 605406960307

Result ✓ Passed

MOT #3 2020-07-08 15:13

MOT test number 874100293336

Result \(\sqrt{Passed} \)

MOT #2 2019-07-11 12:48

MOT test number 459205396711

Result \rightarrow Passed

Advice Front Tyre worn close to legal limit/worn on edge x 2 with considerable tread damage to both tyres (5.2.3 (e))

MOT #1 2018-07-18 14:46

MOT test number 442504125016

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



FE65KXS

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

Plate changes	More info >
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-08
Last registration	2024-02-06
Complete history	See info



Registration #1	2015-09-08	9 mi
Registration #2	2018-07-18	22.777 mi
Registration #3	2019-07-11	32.307 mi
Registration #4	2020-07-08	38.414 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1790 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number1217988