



Mercedes-Benz



report date: 2024-03-28

General information

| | |
|---------------------|---------------------|
| Make | MERCEDES |
| Model | CLK CLK200 ELEGANCE |
| Colour | Black |
| Year of manufacture | 2005 |
| Top speed | 142 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 163 BHP |
| Max. torque | 240 Nm at 3.000 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 21.4 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 31.7 mpg |
| CO2 emission | 206 g/km |
| CO2 label | K |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-09 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-02 |
| MOT pass rate | 70 % |
| MOT passed | 16 |
| Failed MOT tests | 7 |
| Total advice items | 46 |
| Total items failed | 3 |

| | |
|------------------|--|
| MOT #23 | 2024-03-27 14:02 |
| MOT test number | 672795530318 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-02 |
| Advice | Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) |

| | |
|-------------------------|--|
| MOT #22 | 2024-03-27 14:02 |
| MOT test number | 403469003346 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Headlamp aim too low (4.1.2 (a)) |
| Advice | Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) |

| | |
|-----------------|---|
| MOT #21 | 2023-03-24 15:51 |
| MOT test number | 776716161169 |
| Result | ✓ Passed |
| Advice | Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) |
| Advice | Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) |

**MOT #20** 2023-03-24 15:51**MOT test number** 195190339530**Result** ✗ Failed**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #19** 2022-03-09 16:50**MOT test number** 660438765289**Result** ✓ Passed**Minor** Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))**MOT #18** 2022-03-09 15:58**MOT test number** 659661522800**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))**MOT #17** 2021-03-26 10:08**MOT test number** 346783237669**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #16**

2021-03-12 14:54

MOT test number

814856189282

Result**✗ Failed****Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Minor** Front Windscreen damaged but not adversely affecting driver's view crack & chip (3.2 (a) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MOT #15**

2020-03-18 14:38

MOT test number

522019191402

Result**✓ Passed****Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner and outer edge (5.2.3 (d) (ii))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Minor** Windscreen damaged but not adversely affecting driver's view on a zone (3.2 (a) (i))**MOT #14**

2020-03-18 14:22

MOT test number

363768712814

Result**✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view on a zone (3.2 (a) (i))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner and outer edge (5.2.3 (d) (ii))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #13**

2019-03-26 13:46

MOT test number

831039139825

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12**

2019-03-26 10:06

MOT test number

298584282501

Result

✗ Failed

MAJOR Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2018-03-21 11:43

MOT test number

794863132151

Result

✓ Passed

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre cracked and perished

**MOT #10** 2018-03-17 14:55**MOT test number** 269223286808**Result** ✗ Failed**Fail** Offside Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre cracked and perished**MOT #9** 2017-03-21 14:52**MOT test number** 540594448144**Result** ✓ Passed**Advice** Engine cover and tray obstruction under side of ccomponents**MOT #8** 2016-04-03 09:51**MOT test number** 350722376555**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2015-01-15 17:45**MOT test number** 479855815053**Result** ✓ Passed**MOT #6** 2014-01-15 12:53**MOT test number** 105125814485**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)



| | |
|-----------------|------------------|
| MOT #5 | 2012-09-19 09:55 |
| MOT test number | 268633362225 |
| Result | ✓ Passed |
| MOT #4 | 2011-09-22 17:20 |
| MOT test number | 556595261213 |
| Result | ✓ Passed |
| MOT #3 | 2010-09-23 09:30 |
| MOT test number | 992066060211 |
| Result | ✓ Passed |
| MOT #2 | 2009-09-09 11:36 |
| MOT test number | 861072859202 |
| Result | ✓ Passed |
| MOT #1 | 2008-09-06 12:22 |
| MOT test number | 423910358243 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 2 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2005-09-16 |
| Last registration | 2024-03-27 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-09-16 | 24 mi |
| Registration #2 | 2008-09-06 | 14.826 mi |
| Registration #3 | 2009-09-09 | 18.492 mi |
| Registration #4 | 2010-09-23 | 22.166 mi |
| Registration #5 | 2011-09-22 | 26.459 mi |
| Registration #6 | 2012-09-19 | 32.085 mi |
| Registration #7 | 2014-01-15 | 38.595 mi |
| Registration #8 | 2015-01-15 | 42.056 mi |
| Registration #9 | 2016-04-03 | 46.474 mi |
| Registration #10 | 2017-03-21 | 50.367 mi |
| Registration #11 | 2018-03-17 | 53.453 mi |
| Registration #12 | 2018-03-21 | 53.617 mi |
| Registration #13 | 2019-03-26 | 56.970 mi |
| Registration #14 | 2019-03-26 | 56.970 mi |
| Registration #15 | 2019-03-26 | 56.970 mi |
| Registration #16 | 2019-03-26 | 56.970 mi |
| Registration #17 | 2019-03-26 | 56.970 mi |
| Registration #18 | 2019-03-26 | 56.970 mi |
| Registration #19 | 2019-03-26 | 56.970 mi |
| Registration #20 | 2019-03-26 | 56.970 mi |
| Registration #21 | 2019-03-26 | 56.970 mi |
| Registration #22 | 2019-03-26 | 56.970 mi |
| Registration #23 | 2019-03-26 | 56.970 mi |
| Registration #24 | 2019-03-26 | 56.970 mi |
| Registration #25 | 2019-03-26 | 56.970 mi |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1740 mm |
| Height | 1413 mm |
| Length | 4638 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1615 kg |
| Max. allowed weight | 2010 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 27194030536557 |