



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Grey
Year of manufacture	2009
Top speed	148 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	215 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-21
Pictures	70
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-08
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	18
Total items failed	2

MOT #16	2022-09-14 15:37
MOT test number	336596428262
Result	✓ Passed
Next expiry date	2023-10-08
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2022-09-14 14:03
MOT test number	116639633211
Result	✗ Failed
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #14	2021-10-05 07:06
MOT test number	171884356931
Result	✓ Passed

**MOT #13**

2021-09-27 16:12

MOT test number

730382105124

Result**✗ Failed**

- MAJOR** Nearside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #12

2020-10-09 15:47

MOT test number

831297691778

Result**✓ Passed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

2020-10-08 13:58

MOT test number

711833977941

Result**✗ Failed**

- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

2019-05-30 09:30

MOT test number

754053354945

Result**✓ Passed**

- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front bushes of n/s and o/s front arms starting to perish (5.3.4 (a) (i))

**MOT #9** 2019-05-28 08:43**MOT test number** 543744142806**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front bushes of n/s and o/s front arms starting to perish (5.3.4 (a) (i))**MOT #8** 2018-06-05 11:16**MOT test number** 676342709352**Result** ✓ Passed**MOT #7** 2017-06-14 12:05**MOT test number** 533537636038**Result** ✓ Passed**MOT #6** 2016-06-07 09:10**MOT test number** 693444793135**Result** ✓ Passed**Advice** Offside Front TYRE WORN ON INNER EDGE**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-06-20 12:49**MOT test number** 279271075459**Result** ✓ Passed**MOT #4** 2014-10-15 11:48**MOT test number** 205278084291**Result** ✓ Passed



MOT #3	2013-10-29 13:11
MOT test number	889692703374
Result	✓ Passed

MOT #2	2013-10-28 11:17
MOT test number	359771803335
Result	✗ Failed
<div><div>Fail</div>Offside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	
<div><div>Fail</div>Nearside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	

MOT #1	2012-10-31 14:58
MOT test number	269055402302
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-01
Last registration	2022-09-14
Complete history	See info



Registration #1	2009-09-01	14 mi
Registration #2	2012-10-31	15.111 mi
Registration #3	2013-10-28	25.997 mi
Registration #4	2013-10-29	25.997 mi
Registration #5	2014-10-15	36.777 mi
Registration #6	2015-06-20	44.041 mi
Registration #7	2016-06-07	56.733 mi
Registration #8	2017-06-14	75.174 mi
Registration #9	2018-06-05	89.645 mi
Registration #10	2019-06-05	95.337 mi
Registration #11	2019-06-05	95.337 mi
Registration #12	2019-06-05	95.337 mi
Registration #13	2019-06-05	95.337 mi
Registration #14	2019-06-05	95.337 mi
Registration #15	2019-06-05	95.337 mi
Registration #16	2019-06-05	95.337 mi
Registration #17	2019-06-05	95.337 mi
Registration #18	2019-06-05	95.337 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040768187