



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND ESPACE GRAND INITIALE DCI (175) E4
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	360 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.2 mpg
CO2 emission	200 g/km
CO2 label	J





MOT history

MOT expiry date	2021-01-06
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	38
Total items failed	9

MOT #17 2021-01-06 10:09

MOT test number 432762848192

Result ✗ Failed

MAJOR Nearside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Bonnet primary retaining device slightly deteriorated (3.1 (c))

MAJOR Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MAJOR Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

MOT #16 2019-07-03 12:42

MOT test number 192199941494

Result ✓ Passed

**MOT #15** 2019-07-03 08:59**MOT test number** 682495700810**Result** ✗ Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14 2018-06-25 09:47**MOT test number** 984180756255**Result** ✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #13 2018-06-25 08:17**MOT test number** 371993655536**Result** ✗ Failed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12 2017-06-26 15:38**MOT test number** 262476852543**Result** ✓ Passed**MOT #11** 2017-06-22 16:01**MOT test number** 135376474530**Result** ✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10** 2016-07-07 11:06**MOT test number** 149829192546**Result** ✓ Passed**MOT #9** 2016-07-01 08:52**MOT test number** 941830073850**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2015-05-27 14:23**MOT test number** 296877245468**Result** ✓ Passed**Notice** Vacuum hoses to DPF perishing**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)**Advice** Centre Stop lamp damaged, but still visible from a reasonable distance (1.2.1d)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #7**

2015-05-27 14:23

MOT test number

668057145185

Result**✗ Failed****Advice**

Nearside Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Centre Stop lamp damaged, but still visible from a reasonable distance (1.2.1d)

Advice

Nearside Track rod end ball joint has slight play (2.2.B.1f)

Notice

Vacumn hoses to DPF perishing

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #6

2014-05-15 13:13

MOT test number

576275634120

Result**✓ Passed****Advice**

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice

Passenger seat(s) missing at time of test

MOT #5

2014-05-14 14:05

MOT test number

596374334105

Result**✗ Failed****Advice**

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice

Passenger seat(s) missing at time of test

**MOT #4** 2013-05-16 16:27**MOT test number** 228066933492**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-05-04 15:51**MOT test number** 637325522139**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #2** 2011-05-03 10:34**MOT test number** 429203021117**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #1** 2010-04-20 10:15**MOT test number** 170120410170**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
8 January 2021

X

MOT

Expired:
6 January 2021

Tax status	Expired at 8 January 2021
Days left	1207 days too late
MOT expiry date	6 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-26
Last registration	2021-01-06
Complete history	See info



Registration #1	2007-03-26	23 mi
Registration #2	2010-04-20	32.425 mi
Registration #3	2011-05-03	41.598 mi
Registration #4	2012-05-04	54.811 mi
Registration #5	2013-05-16	68.405 mi
Registration #6	2014-05-14	90.023 mi
Registration #7	2014-05-15	90.025 mi
Registration #8	2015-05-27	112.851 mi
Registration #9	2016-07-01	130.409 mi
Registration #10	2016-07-01	130.409 mi
Registration #11	2016-07-01	130.409 mi
Registration #12	2016-07-01	130.409 mi
Registration #13	2016-07-01	130.409 mi
Registration #14	2016-07-01	130.409 mi
Registration #15	2016-07-01	130.409 mi
Registration #16	2016-07-01	130.409 mi
Registration #17	2016-07-01	130.409 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1860 mm
Height	1746 mm
Length	4861 mm
Wheel base	2868 mm
Kerb weight	1830 kg
Max. allowed weight	2610 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	C018368