



MTI70VS

report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Black
Year of manufacture	2017
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	520 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	65.7 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-08-08
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-07
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #6	2023-07-03 14:20
MOT test number	146388260088
Result	✓ Passed
Next expiry date	2024-07-04

MOT #5	2022-06-29 13:20
MOT test number	570153957987
Result	✓ Passed

MOT #4	2021-07-05 15:28
MOT test number	868895791865
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge wearing (5.2.3 (e))
Advice	Items removed from driver's view prior to test
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges wearing (5.2.3 (e))
Advice	Nearside Front Nail in tyre two nails

**MOT #3** 2021-06-26 08:58**MOT test number** 204759833236**Result** ✗ Failed

- Advice** Nearside Front Nail in tyre two nails
- MAJOR** Nearside Front Service brake lagging in operation (1.2.1 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edges wearing (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge wearing (5.2.3 (e))

**MOT #2** 2020-08-24 09:16**MOT test number** 213227830297**Result** ✓ Passed

- Advice** Under guards fitted
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2020-05-04 08:58**MOT test number** 483518581717**Result** ✓ Passed

- Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
4 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	4 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 175,00,-
<b>Standard rate (12 months)</b>	£ 170,00,-
<b>Standard rate (6 months)</b>	£ 93,50,-
<b>Premium rate (12 months)</b>	£ 560,00,-
<b>Premium rate (6 months)</b>	£ 308,00,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-12
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2017-05-12	25 mi
Registration #2	2020-08-24	83.750 mi
Registration #3	2021-06-26	98.685 mi
Registration #4	2021-07-05	98.995 mi
Registration #5	2023-07-03	99.000 mi
Registration #6	2023-07-03	99.000 mi
Registration #7	2023-07-03	99.000 mi
Registration #8	2023-07-03	99.000 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AR1668318