



report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 35 H/R P/V MULTIJET
Colour	White
Year of manufacture	2015
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	2.287 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	40.4 mpg
CO2 emission	183 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-03-02
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	41
Total items failed	11

MOT #11	2024-02-14 15:50
---------	------------------

MOT test number	381191241332
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-15
------------------	------------

- Minor

Nearside Rear Side repeater lens defective which has no effect on emitted light lamp (4.4.1 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor

Offside Front Upper Side repeater lens defective which has no effect on emitted light mirror (4.4.1 (b) (i))
- Advice

Oil light and service light flashing on dash
- Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #10

2024-02-14 15:50

MOT test number

188511039602

Result

✗ Failed

- Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor

Nearside Rear Side repeater lens defective which has no effect on emitted light lamp (4.4.1 (b) (i))
- Advice

Oil light and service light flashing on dash
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification

Nearside Front Headlamp aim too low (4.1.2 (a))
- Pass with rectification

Rear Reversing lamp inoperative (4.6.1 (a))
- Minor

Offside Front Upper Side repeater lens defective which has no effect on emitted light mirror (4.4.1 (b) (i))
- Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2024-02-05 13:07

**MOT test number**

243891377501

**Result****✗ Failed**

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs lipped (1.1.14 (a) (ii))

**Fail** Reversing lamp inoperative (4.6.1 (a))

**Advice** Service brake fluctuating, but not excessively all brakes have slight fluctuation (1.2.1 (e))

**Minor** Offside Side repeater lens defective which has no effect on emitted light no lens (4.4.1 (b) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing + nail in tyre (5.2.3 (d) (ii))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))

**Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light broken lens (4.4.1 (b) (i))

**Fail** Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #8**

2023-02-03 16:11

**MOT test number**

624851230108

**Result****✓ Passed****MOT #7**

2022-02-16 13:53

**MOT test number**

116657404336

**Result****✓ Passed**

**MOT #6**

2021-03-11 10:53

**MOT test number**

939642727595

**Result**

✓ Passed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to legal limit (5.2.3 (e))
- Advice** Rear leaf springs sat on spring assisters, vehicle has adequate wheel to body clearance but appears to be overweight.
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Limited amount of reserve travel on parking brake
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))

**MOT #5**

2021-03-11 10:53

**MOT test number**

918987972008

**Result**

✗ Failed

- Advice** Items removed from driver's view prior to test
- Pass with rectification** Nearside Body component damaged and likely to cause injury Temporary taped repair to sharp edges on mirror casing (6.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))
- Advice** Rear leaf springs sat on spring assisters, vehicle has adequate wheel to body clearance but appears to be overweight.
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to legal limit (5.2.3 (e))
- Advice** Limited amount of reserve travel on parking brake
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))

**MOT #4** 2020-03-18 16:44**MOT test number** 396597991312**Result** ✓ Passed

- Advice** Nearside mirror casing damaged
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear of vehicle sat on bump stops. vehicle maybe over weight
- Advice** Hand brake has slight hand brake travel

**MOT #3** 2019-03-06 08:15**MOT test number** 463096211923**Result** ✓ Passed**MOT #2** 2018-01-24 12:27**MOT test number** 507042309534**Result** ✓ Passed

- Advice** Nearside Rear light cluster cracked

**MOT #1** 2018-01-24 09:17**MOT test number** 918708468517**Result** ✗ Failed

- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
- Advice** Nearside Rear light cluster cracked
- Fail** Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside side repeater lens missing
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
15 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	15 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2024-02-14
Complete history	<a href="#">See info</a>



Registration #1	2015-03-31	29 mi
Registration #2	2018-01-24	54.562 mi
Registration #3	2018-01-24	54.562 mi
Registration #4	2019-03-06	75.302 mi
Registration #5	2020-03-18	90.380 mi
Registration #6	2021-03-11	98.759 mi
Registration #7	2021-03-11	98.759 mi
Registration #8	2022-03-20	98.759 mi
Registration #9	2022-03-20	98.759 mi
Registration #10	2022-03-20	98.759 mi
Registration #11	2022-03-20	98.759 mi
Registration #12	2022-03-20	98.759 mi
Registration #13	2024-02-14	29 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	2524 mm
Length	5998 mm
Kerb weight	1975 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	2292286