



report date: 2024-03-29

General information

Make	VAUXHALL
Model	CROSSLAND ELITE NAV
Colour	Red
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 4

Date	2021-08-24
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 3



Date	2021-08-19
Pictures	19
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

Entry 2

Date	2021-08-15
Pictures	20
Listing price	View report



source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 1

Date	2021-07-31
------	------------

Pictures

0

Listing price

[View report](#)

source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-03-08
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5 2024-02-15 10:10**MOT test number** 290019447172**Result** Passed**Next expiry date** 2025-03-08

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust mounting defective near flexi (6.1.2 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2023-02-17 15:02**MOT test number** 621649694122**Result** Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2022-02-17 14:34**MOT test number** 970310324731**Result** ✓ Passed**Advice** Both rear bumper stops are missing**MOT #2** 2021-03-09 09:59**MOT test number** 458133269490**Result** ✓ Passed**Advice** Items removed from driver's view prior to test zone a (camera)**MOT #1** 2021-03-09 09:59**MOT test number** 800362810741**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (4.1.2 (a))**Advice** Items removed from driver's view prior to test zone a (camera)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 March 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YC18KGX
Plate since	2019-06-29
Current registration	 YC18KGX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-05-21
Last registration	2024-02-15
Complete history	See info



Registration #1	2018-05-21	17 mi
Registration #2	2021-03-09	12.908 mi
Registration #3	2021-03-09	12.908 mi
Registration #4	2021-03-09	12.908 mi
Registration #5	2021-03-09	12.908 mi
Registration #6	2021-03-09	12.908 mi
Registration #7	2021-03-09	12.908 mi
Registration #8	2021-03-09	12.908 mi
Registration #9	2021-03-09	12.908 mi
Registration #10	2021-03-09	12.908 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	84%
Pedestrian	62%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1976 mm
Height	1597 mm
Length	4212 mm
Wheel base	2604 mm
Kerb weight	1099 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	10XVDA0035991 LEZ