



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	2
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2023-03-09 08:14
MOT test number	211226376514
Result	✓ Passed
Next expiry date	2024-03-31

MOT #19	2022-03-21 14:37
MOT test number	122464182989
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2021-03-27 10:05
MOT test number	686391286313
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt X2
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Headlamp lens slightly defective Both (4.1.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge On 1.6mm and badly perished (5.2.3 (e))

**MOT #17**

2021-03-27 10:05

MOT test number

713263941686

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge On 1.6mm and badly perished (5.2.3 (e))**Pass with rectification** Windscreen washer provides insufficient washer liquid Both (3.5 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt X2**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Headlamp lens slightly defective Both (4.1.1 (b) (i))**MOT #16**

2020-03-26 16:48

MOT test number

346739450168

Result**✓ Passed****Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))**Advice** Exhaust has a minor leak of exhaust gases Rear section (6.1.2 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2020-03-26 09:17

MOT test number

595944500225

Result**✗ Failed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases Rear section (6.1.2 (a))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Rear Seat belt buckle not functioning as intended Centre row (7.1.2 (d))
- Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2019-03-29 16:19

MOT test number

174420231402

Result**✓ Passed**

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Slight oil leak
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13**

2019-03-29 11:19

MOT test number

869676950855

Result**✗ Failed****Fail** Emissions not tested (8.2.2.2 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Slight oil leak**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Exhaust has a major leak of exhaust gases rear of centre section (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge + inner edge 0mm (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12**

2018-03-19 10:18

MOT test number

526370273454

Result**✓ Passed****MOT #11**

2017-03-25 09:00

MOT test number

531520062783

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2017-03-24 16:40**MOT test number** 847189828782**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2016-04-01 11:43**MOT test number** 417478322464**Result** ✓ Passed**Advice** Centre Rear Upper Stop light in-op**MOT #8** 2015-03-24 16:13**MOT test number** 249093085088**Result** ✓ Passed**MOT #7** 2014-03-28 14:04**MOT test number** 525337784068**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2014-03-26 09:04**MOT test number** 928615584026**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2013-03-06 08:17**MOT test number** 625925763023**Result** ✓ Passed**MOT #4** 2013-03-02 10:59**MOT test number** 459921763099**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2012-02-07 12:56**MOT test number** 545598032074**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-31 08:26**MOT test number** 674635660359**Result** ✓ Passed**Notice** Both the front and the rear number plates are starting to delaminate.**MOT #1** 2010-12-30 10:32**MOT test number** 710934460350**Result** ✗ Failed**Notice** Nearside rear adult seat belt not tested as child seat fitted.**Notice** Traction control light on.**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Notice** Both the front and the rear number plates are starting to delaminate.



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-01-22
Last registration	2023-03-09
Complete history	See info



Registration #1	2008-01-22	7 mi
Registration #2	2010-12-30	66.605 mi
Registration #3	2010-12-31	66.675 mi
Registration #4	2012-02-07	81.008 mi
Registration #5	2013-03-02	91.407 mi
Registration #6	2013-03-06	91.407 mi
Registration #7	2014-03-26	99.703 mi
Registration #8	2014-03-28	99.705 mi
Registration #9	2015-03-24	108.501 mi
Registration #10	2016-04-01	118.985 mi
Registration #11	2017-03-24	130.930 mi
Registration #12	2018-03-29	142.875 mi
Registration #13	2019-03-29	154.820 mi
Registration #14	2020-03-29	166.765 mi
Registration #15	2021-03-29	178.710 mi
Registration #16	2022-03-29	190.655 mi
Registration #17	2023-03-29	202.600 mi
Registration #18	2024-03-29	214.545 mi
Registration #19	2025-03-29	226.490 mi
Registration #20	2026-03-29	238.435 mi
Registration #21	2027-03-29	250.380 mi
Registration #22	2028-03-29	262.325 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1904 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8B04464