



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE ECO
Colour	White
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2021-12-02
MOT pass rate	53 %
MOT passed	9
Failed MOT tests	8
Total advice items	26
Total items failed	29

MOT #17	2020-11-14 10:12
MOT test number	277595421477
Result	✓ Passed
Next expiry date	2021-12-02
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2020-11-06 07:17
MOT test number	247033809127
Result	✗ Failed
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-11-30 11:36
MOT test number	408050036071
Result	✓ Passed

**MOT #14** 2019-11-27 14:53**MOT test number** 355285232443**Result** ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Exhaust has a major leak of exhaust gases front joint (6.1.2 (a))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13 2018-11-21 12:09**MOT test number** 906991560227**Result** ✓ Passed**MOT #12** 2018-11-21 10:20**MOT test number** 685497380031**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2017-11-17 16:20

MOT test number

754194051873

Result

✓ Passed

- Advice** Brake pipes corroded
- Advice** Rear coil springs corroded
- Advice** Offside Front shocker damp

MOT #10

2017-11-17 11:20

MOT test number

841901467084

Result

✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Offside Front shocker damp
- Advice** Brake pipes corroded
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Exhaust corroded
- Advice** Rear coil springs corroded
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9

2016-11-25 14:57

MOT test number

910412876682

Result

✓ Passed

- Advice** Front brake discs worn
- Advice** Corrosion to exhaust

**MOT #8**

2016-11-25 09:57

MOT test number

777305001419

Result**✗ Failed****Fail** Front brake application uneven (3.7.B.2)**Advice** Front brake discs worn**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Corrosion to exhaust**Advice** Both front lower arm rear bushes becoming un bonded and have slight movement**MOT #7**

2015-12-03 14:27

MOT test number

197245229283

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #6**

2015-12-02 12:00

MOT test number

179393213549

Result**✗ Failed****Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)**Fail** Nearside Headlamp insecure (1.7.3)

**MOT #5** 2014-11-05 08:44**MOT test number** 465469704410**Result** ✓ Passed**MOT #4** 2014-11-04 08:40**MOT test number** 467108604428**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside rear brake binding (3.7.B.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-11-15 08:46**MOT test number** 735719713339**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2012-11-02 15:56**MOT test number** 416807602444**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-11-02 11:10**MOT test number** 247987002339**Result** ✗ Failed**Fail** Nearside Headlamp insecure (1.7.3)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YH59WNB
Plate since	2019-09-29
Current registration	YH59WNB
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-06
Last registration	2020-11-14
Complete history	See info



Registration #1	2009-11-06	18 mi
Registration #2	2012-11-02	32.800 mi
Registration #3	2012-11-02	32.800 mi
Registration #4	2013-11-15	22.382 mi
Registration #5	2014-11-04	42.710 mi
Registration #6	2014-11-05	42.719 mi
Registration #7	2015-12-02	46.819 mi
Registration #8	2015-12-03	46.839 mi
Registration #9	2016-11-25	51.121 mi
Registration #10	2016-11-25	51.121 mi
Registration #11	2016-11-25	51.121 mi
Registration #12	2016-11-25	51.121 mi
Registration #13	2016-11-25	51.121 mi
Registration #14	2016-11-25	51.121 mi
Registration #15	2016-11-25	51.121 mi
Registration #16	2016-11-25	51.121 mi
Registration #17	2016-11-25	51.121 mi
Registration #18	2016-11-25	51.121 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	5307642