



report date: 2024-03-28

General information

Make	HONDA
Model	JAZZ I-VTEC SPORT
Colour	Black
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	155 Nm at 4.600 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #6	2023-05-27 09:49
MOT test number	196283373725
Result	✓ Passed
Next expiry date	2024-06-08
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #5	2023-05-20 09:16
MOT test number	970458331495
Result	✗ Failed
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Fail	Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

MOT #4	2022-06-07 16:13
MOT test number	670504868299
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #3** 2022-05-26 16:54**MOT test number** 617853030805**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Front fog lamp not working (4.5.1 (a) (ii))**MOT #2** 2021-06-09 07:10**MOT test number** 473740089589**Result** ✓ Passed**MOT #1** 2021-06-04 15:02**MOT test number** 219787160555**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Cuts with stones embedded and tyre wearing low on inner edge (5.2.3 (d) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Cuts with stones embedded (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-10-31
Last registration	2023-05-27
Complete history	See info



Registration #1	2018-10-31	17 mi
Registration #2	2021-06-04	20.895 mi
Registration #3	2021-06-09	20.896 mi
Registration #4	2023-05-27	20.897 mi
Registration #5	2023-05-27	20.897 mi
Registration #6	2023-05-27	20.897 mi
Registration #7	2023-05-27	20.897 mi
Registration #8	2023-05-27	20.897 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	85%
Pedestrian	73%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1694 mm
Height	1550 mm
Length	4051 mm
Wheel base	2530 mm
Kerb weight	1116 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L15B33130718