



report date: 2024-03-29

General information

| | |
|---------------------|-----------------|
| Make | FORD |
| Model | FIESTA TITANIUM |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 109 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 95 BHP |
| Max. torque | 128 Nm at 4.200 rpm |
| Engine capacity | 1.388 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 133 g/km |
| CO2 label | E |







Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-10-29 |
| Pictures | 50 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-28 |
| Pictures | 57 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-14 |
| MOT pass rate | 71 % |
| MOT passed | 12 |
| Failed MOT tests | 5 |
| Total advice items | 19 |
| Total items failed | 6 |

MOT #17 2023-11-15 17:57

MOT test number 601837849899

Result ✓ Passed

Next expiry date 2024-11-14

- Advice** Tyre worn close to legal limit/worn on edge All (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Exhaust shows slight corrosion

MOT #16 2022-10-27 14:06

MOT test number 206640143806

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-10-26 08:15

MOT test number 953269135858

Result ✗ Failed

- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-11-12 16:03**MOT test number** 220221534715**Result** ✓ Passed**MOT #13** 2021-11-09 11:50**MOT test number** 669287318055**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn ARM FRONT BUSH (5.3.4 (a) (i))**DANGEROUS** Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2020-11-04 09:35**MOT test number** 466600834311**Result** ✓ Passed**MOT #11** 2020-11-04 09:35**MOT test number** 484311766338**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too far to the left (4.1.2 (a))**Pass with rectification** Central Exhaust system insecure (6.1.2 (a))**MOT #10** 2019-11-08 11:27**MOT test number** 316124126631**Result** ✓ Passed

**MOT #9** 2018-11-05 09:34**MOT test number** 748484556005**Result** ✓ Passed**Advice** Exhaust heat shield insecure**MOT #8** 2018-11-05 09:34**MOT test number** 792005165298**Result** ✗ Failed**Pass with rectification** Front Position lamp not working (4.2.1 (a))**Advice** Exhaust heat shield insecure**MOT #7** 2017-11-15 12:00**MOT test number** 988127995486**Result** ✓ Passed**MOT #6** 2017-06-30 13:50**MOT test number** 869288478327**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-06-30 09:49**MOT test number** 773283004947**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #4** 2016-06-30 08:57**MOT test number** 432393576161**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #3** 2015-07-06 09:15**MOT test number** 235397885176**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #2** 2014-07-08 12:44**MOT test number** 209739884473**Result** ✓ Passed**MOT #1** 2013-07-05 10:15**MOT test number** 649176683174**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 126 |
| MOT expiry date | 14 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2023-03-29 |
| Current registration | ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2010-07-08 |
| Last registration | 2023-11-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-07-08 | 27 mi |
| Registration #2 | 2013-07-05 | 24.861 mi |
| Registration #3 | 2014-07-08 | 33.463 mi |
| Registration #4 | 2015-07-06 | 40.348 mi |
| Registration #5 | 2016-06-30 | 48.414 mi |
| Registration #6 | 2017-06-30 | 56.763 mi |
| Registration #7 | 2017-06-30 | 56.763 mi |
| Registration #8 | 2017-11-15 | 59.638 mi |
| Registration #9 | 2018-11-05 | 60.786 mi |
| Registration #10 | 2018-11-05 | 60.786 mi |
| Registration #11 | 2019-06-30 | 61.277 mi |
| Registration #12 | 2019-06-30 | 61.277 mi |
| Registration #13 | 2019-06-30 | 61.277 mi |
| Registration #14 | 2019-06-30 | 61.277 mi |
| Registration #15 | 2019-06-30 | 61.277 mi |
| Registration #16 | 2019-06-30 | 61.277 mi |
| Registration #17 | 2019-06-30 | 61.277 mi |
| Registration #18 | 2019-06-30 | 61.277 mi |
| Registration #19 | 2019-06-30 | 61.277 mi |
| Registration #20 | 2019-06-30 | 61.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1973 mm |
| Height | 1481 mm |
| Length | 3950 mm |
| Wheel base | 2489 mm |
| Kerb weight | 1041 kg |
| Max. allowed weight | 1495 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 42 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 9E63133 |