



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D SPORT S40
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2020-12-10
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	21
Total items failed	3

MOT #12	2019-06-11 10:25
MOT test number	534985208035
Result	✓ Passed
Next expiry date	2020-12-10

MOT #11	2018-05-23 07:43
MOT test number	390226411550
Result	✓ Passed

- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2018-05-22 08:10

**MOT test number**

274738589816

**Result**

✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9**

2017-05-23 15:30

**MOT test number**

112039383002

**Result**

✓ Passed

**Advice** Small crack in n\s of windscreen**MOT #8**

2016-05-16 16:01

**MOT test number**

649610417314

**Result**

✓ Passed

**MOT #7**

2015-04-30 16:16

**MOT test number**

577530225196

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2014-04-01 11:29**MOT test number** 655571494095**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Centre exhaust deteriorated and rear exhaust hanger broken but still secure**MOT #5** 2013-01-09 13:00**MOT test number** 728459403022**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-11-04 12:38**MOT test number** 199228501353**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #3** 2010-11-03 10:33**MOT test number** 101137000373**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-11-03 09:16
MOT test number	354467809367
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2008-09-30 11:38
MOT test number	620484078252
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2005-11-03
Last registration	2019-06-11
Complete history	<a href="#">See info</a>



Registration #1	2005-11-03	10 mi
Registration #2	2008-09-30	75.866 mi
Registration #3	2009-11-03	96.464 mi
Registration #4	2010-11-03	113.664 mi
Registration #5	2011-11-04	126.938 mi
Registration #6	2013-01-09	151.044 mi
Registration #7	2014-04-01	173.156 mi
Registration #8	2015-06-20	191.277 mi
Registration #9	2016-06-20	201.277 mi
Registration #10	2017-06-20	211.277 mi
Registration #11	2018-06-20	221.277 mi
Registration #12	2019-06-11	231.277 mi
Registration #13	2020-06-20	241.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	4002000
---------------	---------