



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH DSIGN
Colour	Grey
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-07
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-06
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	14
Total items failed	12

MOT #12	2023-09-04 12:05
MOT test number	346382683481
Result	✓ Passed
Next expiry date	2024-09-06

MOT #11	2023-08-29 07:38
MOT test number	293342928411

Result	✗ Failed
--------	----------

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides cracked , split ,not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Drive belt defective parts of belt missing

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))

**MOT #10** 2022-09-07 07:14**MOT test number** 551236628534**Result** ✓ Passed**MOT #9** 2022-09-02 06:52**MOT test number** 509385925484**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2021-12-10 14:16**MOT test number** 879323514992**Result** ✓ Passed**MOT #7** 2021-12-01 08:54**MOT test number** 149749263845**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front fog light inop**MOT #6** 2021-04-02 14:49**MOT test number** 576405353422**Result** ✓ Passed

**MOT #5** 2021-04-02 12:33**MOT test number** 893227289156**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2020-03-27 12:52**MOT test number** 283498667429**Result** ✓ Passed**MOT #3** 2019-03-27 15:06**MOT test number** 128267085524**Result** ✓ Passed**Advice** Offside Front fog lamp inop**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2019-03-22 16:22**MOT test number** 428652128527**Result** ✗ Failed**Fail** Front Exhaust system insecure (6.1.2 (a))**Advice** Offside Front fog lamp inop**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2018-03-10 16:19**MOT test number** 174105745431**Result** ✓ Passed**Advice** Rear exhaust clamp broken**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
6 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	6 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-03-16
Last registration	2023-09-04
Complete history	<a href="#">See info</a>



Registration #1	2015-03-16	13 mi
Registration #2	2018-03-10	24.483 mi
Registration #3	2019-03-22	31.120 mi
Registration #4	2019-03-27	31.205 mi
Registration #5	2020-03-27	39.849 mi
Registration #6	2021-04-02	48.537 mi
Registration #7	2021-04-02	48.537 mi
Registration #8	2022-03-22	55.277 mi
Registration #9	2022-03-22	55.277 mi
Registration #10	2022-03-22	55.277 mi
Registration #11	2022-03-22	55.277 mi
Registration #12	2022-03-22	55.277 mi
Registration #13	2022-03-22	55.277 mi
Registration #14	2023-09-04	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1496 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B2080349442