



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Black
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 2

Date	2022-02-16
Pictures	17
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

Entry 1

Date	2021-01-30
Pictures	0
Listing price	<a href="#">View report</a>

source: [yesauto.com](#)

**MOT history**

<b>MOT expiry date</b>	2023-01-14
<b>MOT pass rate</b>	100 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	0
<b>Total advice items</b>	15
<b>Total items failed</b>	0

**MOT #6** 2022-01-14 14:56**MOT test number** 615108535927**Result** ✓ Passed**Next expiry date** 2023-01-14

- Advice** Offside Rear Suspension component pin or bush slightly worn trail arm (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Suspension component pin or bush slightly worn trail arm (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #5** 2021-01-15 09:21**MOT test number** 317334003390**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2019-12-16 11:32**MOT test number** 391042342442**Result** ✓ Passed

**MOT #3** 2018-09-18 10:03**MOT test number** 308497777549**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge And slight cracks in tread (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge And slight cracks in tread (5.2.3 (e))**MOT #2** 2017-09-22 13:41**MOT test number** 200400910701**Result** ✓ Passed**Advice** Engine covers fitted**Advice** Nearside Rear Nail in tyre**Advice** Under trays fitted**Advice** Offside Rear Nail in tyre**MOT #1** 2016-09-23 09:39**MOT test number** 963576982465**Result** ✓ Passed**Advice** Under trays fitted obscuring some components



Tax & MOT check

✕  
Untaxed

Tax expired:  
29 March 2023

✕  
MOT

Expired:  
14 January 2023

Tax status	Expired at 29 March 2023
Days left	397 days too late
MOT expiry date	14 January 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX13VTL
Plate since	2019-09-28
Current registration	YX13VTL
Plate since	2019-09-28

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2013-03-28
Last registration	2022-01-14
Complete history	<a href="#">See info</a>



Registration #1	2013-03-28	23 mi
Registration #2	2016-09-23	62.744 mi
Registration #3	2017-09-22	66.728 mi
Registration #4	2018-09-18	71.365 mi
Registration #5	2019-12-16	75.434 mi
Registration #6	2020-05-20	76.277 mi
Registration #7	2020-05-20	76.277 mi
Registration #8	2020-05-20	76.277 mi
Registration #9	2022-01-14	76.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259958
---------------	---------