





report date: 2024-03-28

## General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Green
Year of manufacture	2015
Top speed	153 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	231 BHP
Max. torque	320 Nm at 4.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28


# Internet history

## Entry 1


Date 2021-07-24

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-02
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	6
Total items failed	15

MOT #10	2023-09-22 12:58
MOT test number	598562508688
Result	<b>✓</b> Passed
Next expiry date	2024-10-02
Advice Offside Rear tyre tread starting to twist	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2022-10-03 10:46
MOT test number	746117920968
Result	✓ Passed
MOT #8	2022-09-20 14:43
MOT test number	855531278435
Result	<b>X</b> Failed

Fai	Horn not working (7.7 (a))
Fai	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Fai	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #7	2021-09-24 13:35
MOT test number	508457259607
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



(a))

ST65GME

report date: 2024-03-28

MOT test number

Result

Kesult

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2)

Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

 MOT #5
 2021-09-08 15:43

 MOT test number
 552075104223

 Result
 X Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn Wishbone (5.3.4 (a) (i))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Front Service brake excessively fluctuating (1.2.1 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Brake discs corroded (1.1.14 (a) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (8.1.1 (a))

MOT #4 2021-08-06 13:21
MOT test number 175884288162

Result × Failed

**Advice** Rear Service brake binding but not excessively (1.2.1 (f))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

CarCheck.co.uk page 4/12



ST65GME report date: 2024-03-28

MOT #3

MOT test number

Fesult

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2019-09-18 14:39
MOT test number	646813053279
Result	✓ Passed
MOT #1	2018-10-25 08:07
MOT test number	856481295848
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



ST65GME report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	2 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



ST65GME report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		?
**********		
***************************************		
************		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	NE NE	
Plate since	1111	mm
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-10-09
Last registration	2023-09-22
Complete history	See info



Registration #1	2015-10-09	21 mi
Registration #2	2018-10-25	14.755 mi
Registration #3	2019-09-18	15.770 mi
Registration #4	2020-09-15	31.719 mi
Registration #5		11.777 es
Registration #6	2021-08-06	47.599 mi
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		71.777 es
Registration #11		0.70 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



# Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1280 kg
Max. allowed weight	1685 kg

# Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 1	L2/12