



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | TOYOTA |
| Model | MR2 ROADSTER |
| Colour | Silver |
| Year of manufacture | 2005 |
| Top speed | 130 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 170 Nm at 4.200 rpm |
| Engine capacity | 1.794 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.0 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 178 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-26 |
| Pictures | 11 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-06 |
| MOT pass rate | 75 % |
| MOT passed | 15 |
| Failed MOT tests | 5 |
| Total advice items | 19 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #20 | 2023-05-19 07:03 |
| MOT test number | 896389990214 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-06 |

| | |
|-----------------|--|
| MOT #19 | 2023-05-12 08:58 |
| MOT test number | 564345218525 |
| Result | ✗ Failed |
| Fail | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #18 | 2022-05-13 16:58 |
| MOT test number | 475115713655 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #17 | 2022-05-10 07:49 |
| MOT test number | 370918945466 |
| Result | ✗ Failed |
| Fail | Main beam tell-tale not working (4.9.1 (a) (ii)) |

**MOT #16** 2021-06-07 08:55**MOT test number** 447712944868**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2021-06-07 08:55**MOT test number** 183561327006**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2020-07-23 15:09**MOT test number** 486544651784**Result** ✓ Passed**Advice** Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #13** 2019-07-04 09:12**MOT test number** 143193597934**Result** ✓ Passed**MOT #12** 2018-05-24 13:41**MOT test number** 196433039798**Result** ✓ Passed**MOT #11** 2016-09-16 07:29**MOT test number** 349517608962**Result** ✓ Passed

**MOT #10** 2015-09-15 15:34**MOT test number** 943174354282**Result** ✓ Passed**Advice** O/s rear tyre tread just starting to perish**Advice** O/s front suspension strut shaft pitted**MOT #9** 2015-09-15 15:34**MOT test number** 786877954258**Result** ✗ Failed**Advice** O/s rear tyre tread just starting to perish**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** O/s front suspension strut shaft pitted**MOT #8** 2014-08-19 12:02**MOT test number** 466151434239**Result** ✓ Passed**MOT #7** 2013-08-19 14:36**MOT test number** 297951433298**Result** ✓ Passed**MOT #6** 2012-09-10 11:06**MOT test number** 117064852222**Result** ✓ Passed

**MOT #5** 2011-09-15 09:29**MOT test number** 359828851463**Result** ✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** Nearside rear tyre treads cracking centre treads.
- Notice** Offside rear tyre slight cracking centre treads.

MOT #4 2010-09-15 12:17**MOT test number** 784838550291**Result** ✓ Passed**MOT #3** 2009-09-18 17:00**MOT test number** 593321069217**Result** ✓ Passed

- Notice** Advise nearside front tyre been repaired on outer tread block
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc slightly pitted (3.5.1h)
- Notice** Advise rear number plate in poor condition
- Advice** Nearside Front brake disc slightly pitted (3.5.1h)

MOT #2 2008-09-19 14:40**MOT test number** 763093868222**Result** ✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** N/s/f tyre worn low & o/s/r



| | |
|-----------------|--|
| MOT #1 | 2008-09-19 09:27 |
| MOT test number | 743863868207 |
| Result | ✗ Failed |
| Fail | Parking brake lever has no reserve travel (3.1.6b) |
| Notice | Nail in nearside rear tyre |
| Notice | N/s/f tyre worn low & o/s/r |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 6 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | GY55KXC |
| Plate since | 2019-03-29 |
| Current registration | GY55KXC |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2005-09-12 |
| Last registration | 2023-05-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-09-12 | 19 mi |
| Registration #2 | 2008-09-19 | 25.503 mi |
| Registration #3 | 2008-09-19 | 25.503 mi |
| Registration #4 | 2009-09-18 | 33.501 mi |
| Registration #5 | 2010-09-15 | 40.819 mi |
| Registration #6 | 2011-09-15 | 50.192 mi |
| Registration #7 | 2012-09-10 | 58.817 mi |
| Registration #8 | 2013-08-19 | 63.426 mi |
| Registration #9 | 2014-08-19 | 67.225 mi |
| Registration #10 | 2015-09-15 | 73.205 mi |
| Registration #11 | 2015-09-15 | 73.205 mi |
| Registration #12 | 2016-05-20 | 75.207 mi |
| Registration #13 | 2016-05-20 | 75.207 mi |
| Registration #14 | 2016-05-20 | 75.207 mi |
| Registration #15 | 2016-05-20 | 75.207 mi |
| Registration #16 | 2016-05-20 | 75.207 mi |
| Registration #17 | 2016-05-20 | 75.207 mi |
| Registration #18 | 2016-05-20 | 75.207 mi |
| Registration #19 | 2016-05-20 | 75.207 mi |
| Registration #20 | 2016-05-20 | 75.207 mi |
| Registration #21 | 2016-05-20 | 75.207 mi |
| Registration #22 | 2016-05-20 | 75.207 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1695 mm |
| Height | 1240 mm |
| Length | 3885 mm |
| Wheel base | 2450 mm |
| Kerb weight | 960 kg |
| Max. allowed weight | 1225 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 1ZZ2227752 |