



HYUNDAI

MWI3NFN

report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 2


Date	2021-06-26
Pictures	37
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-17
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	26
Total items failed	1

MOT #14	2023-07-18 12:01
MOT test number	652585020391
Result	✓ Passed
Next expiry date	2024-07-17
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))

MOT #13	2023-07-18 09:18
MOT test number	917202663255
Result	✗ Failed
Advice	Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12**

2022-06-21 14:33

**MOT test number**

167204000651

**Result**

✓ Passed

- Advice** Nearside Front tread damaged in places
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Inner bead of alloy wheel slightly buckled
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #11**

2022-06-21 11:08

**MOT test number**

246833447111

**Result**

✗ Failed

- Advice** Nearside Front tread damaged in places
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Inner bead of alloy wheel slightly buckled
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #10**

2021-07-17 07:09

**MOT test number**

597039854420

**Result**

✓ Passed

**MOT #9**

2021-07-14 08:36

**MOT test number**

122406785690

**Result**

✗ Failed

- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #8** 2020-09-07 10:27**MOT test number** 678590070668**Result** ✓ Passed**MOT #7** 2020-09-02 09:09**MOT test number** 934701346517**Result** ✗ Failed**DANGEROUS** Front Tyre tread depth below requirements of 1.6mm n/s and o/s (5.2.3 (e))**MOT #6** 2019-04-30 13:23**MOT test number** 500848156838**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing in very poor condition req replacement (5.2.3 (d) (ii))**MOT #5** 2019-04-30 09:56**MOT test number** 665595872704**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing in very poor condition req replacement (5.2.3 (d) (ii))**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #4** 2018-05-04 07:53**MOT test number** 793339792534**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #3	2018-05-04 07:53
MOT test number	983660189842
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2	2017-05-10 13:20
MOT test number	124759370750
Result	✓ Passed

MOT #1	2016-06-06 13:21
MOT test number	884932107019
Result	✓ Passed
Advice	Engine cover fitted
Advice	Under trays fitted



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
17 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	17 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2023-03-28
Current registration	<b>XXXXXX</b>
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-06-28
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2013-06-28	6 mi
Registration #2	2016-06-06	9.754 mi
Registration #3	2017-05-10	16.613 mi
Registration #4	2018-05-04	33.762 mi
Registration #5	2018-05-04	33.762 mi
Registration #6	2019-04-30	50.008 mi
Registration #7	2019-04-30	50.008 mi
Registration #8	2020-09-02	65.114 mi
Registration #9	2020-09-07	65.114 mi
Registration #10	2020-09-07	65.114 mi
Registration #11	2020-09-07	65.114 mi
Registration #12	2020-09-07	65.114 mi
Registration #13	2020-09-07	65.114 mi
Registration #14	2020-09-07	65.114 mi
Registration #15	2020-09-07	65.114 mi
Registration #16	2020-09-07	65.114 mi
Registration #17	2020-09-07	65.114 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDDU359760