



RENAULT

SA64YZN


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Grey
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-09-21
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-20
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	16
Total items failed	11

MOT #12	2023-08-21 09:36
MOT test number	722625291860
Result	✓ Passed
Next expiry date	2024-08-20
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2023-08-18 11:12

MOT test number

772818221431

Result**✗ Failed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10**

2022-04-13 13:44

MOT test number

470710640012

Result**✓ Passed****MOT #9**

2022-04-11 11:31

MOT test number

197320808242

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2021-04-20 10:17**MOT test number** 214554291629**Result** ✓ Passed**MOT #7** 2021-04-20 09:01**MOT test number** 116350177603**Result** ✗ Failed

Fail Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

MOT #6 2020-09-15 13:27**MOT test number** 976386734311**Result** ✓ Passed**MOT #5** 2020-09-15 10:32**MOT test number** 589616372311**Result** ✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #4 2019-09-19 11:13**MOT test number** 797010640716**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2019-09-17 15:01**MOT test number** 114000774785**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2018-09-17 09:09**MOT test number** 227303761472**Result** ✓ Passed**MOT #1** 2017-09-07 14:03**MOT test number** 455638820032**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened binding (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-22
Last registration	2023-08-21
Complete history	See info



Registration #1	2014-09-22	17 mi
Registration #2	2017-09-07	51.108 mi
Registration #3	2018-09-17	62.752 mi
Registration #4	2019-09-17	75.474 mi
Registration #5	2019-09-19	75.544 mi
Registration #6	2020-09-15	84.706 mi
Registration #7	2020-09-15	84.706 mi
Registration #8	2020-09-15	84.706 mi
Registration #9	2020-09-15	84.706 mi
Registration #10	2020-09-15	84.706 mi
Registration #11	2020-09-15	84.706 mi
Registration #12	2020-09-15	84.706 mi
Registration #13	2020-09-15	84.706 mi
Registration #14	2020-09-15	84.706 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	D510601