



HYUNDAI



EF64UZL

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | HYUNDAI |
| Model | IX35 CRDI SE |
| Colour | Blue |
| Year of manufacture | 2014 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 114 BHP |
| Max. torque | 260 Nm at 1.250 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-08-12 |
| Pictures | 49 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-10 |
| Pictures | 81 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-15 |
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 30 |
| Total items failed | 1 |

| | |
|------------------|--|
| MOT #10 | 2023-08-04 13:31 |
| MOT test number | 832754336005 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-15 |
| Advice | The emissions limits were tested and met but the DSM could not register the reading. |
| Advice | Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

**MOT #9**

2022-07-28 15:17

MOT test number

825022161432

Result

✓ Passed

- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Emissions tested and passed, readings too low to be registered by DSM
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2021-08-16 09:43

MOT test number

826897674397

Result

✓ Passed

MOT #7

2021-08-14 15:43

MOT test number

978059825078

Result

✗ Failed

- MAJOR** Rear fog lamp switch not operating in accordance with the requirements (4.5.3 (a))
- MAJOR** Rear fog lamp switch inoperative (4.5.3 (a))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively both wipers (3.4 (b) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #6** 2020-12-31 09:45**MOT test number** 210842558805**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2019-12-27 15:28**MOT test number** 696038674249**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #4** 2018-11-30 13:58**MOT test number** 933842476648**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre wearing on inner edge**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2018-11-30 09:52**MOT test number** 729437449140**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre wearing on inner edge**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2017-12-27 13:00**MOT test number** 793042147621**Result** ✓ Passed**MOT #1** 2017-12-27 13:00**MOT test number** 166965348057**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
15 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 248 |
| MOT expiry date | 15 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,200 |
| Auction value | £ 19,200 |
| Average private trade value | £ 19,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2014-12-29 |
| Last registration | 2023-08-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-12-29 | 10 mi |
| Registration #2 | 2017-12-27 | 37.324 mi |
| Registration #3 | 2017-12-27 | 37.324 mi |
| Registration #4 | 2018-11-30 | 49.998 mi |
| Registration #5 | 2018-11-30 | 49.998 mi |
| Registration #6 | 2019-12-27 | 66.381 mi |
| Registration #7 | 2020-12-31 | 74.780 mi |
| Registration #8 | 2020-12-31 | 74.780 mi |
| Registration #9 | 2020-12-31 | 74.780 mi |
| Registration #10 | 2020-12-31 | 74.780 mi |
| Registration #11 | 2020-12-31 | 74.780 mi |
| Registration #12 | 2020-12-31 | 74.780 mi |
| Registration #13 | 2020-12-31 | 74.780 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1820 mm |
| Height | 1665 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1537 kg |
| Max. allowed weight | 1940 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 58 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FDEZ258681 |