





## General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	White
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







# Internet history

Entry 1

Date Pictures 2022-01-03

20

Listing price

View report









source: yesauto.com



## MOT history

MOT expiry date	2024-01-03
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	28
Total items failed	1

MOT #12		2022-12-05 16:15
MOT test	number	319210643852
Result		✓ Passed
Next expi	ry date	2024-01-03
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

#### MOT #11 2022-12-05 09:55 **MOT test number** 368075752281 Result × Failed Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))





MOT #10		2022-01-04 15:07
MOT test	number	250582419402
Result		✓ Passed
MOT #9		2021-12-16 13:13
MOT test	number	908220459243
Result		🗙 Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #8		2020-11-26 12:54
MOT test	number	344772151792
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2019-11-01 09:31
MOT test number	853039827380
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2019-06-26 08:53
MOT test	number	428230825721
Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))





MOT #5		2018-07-25 13:47
MOT test	number	783683238796
Result		✓ Passed
Advice	Nearside Rear tyre cracking	
MOT #4		2018-07-25 07:27
MOT test	number	485011438505
Result		🗙 Failed
Advice	Offside Rear Nail in tyre and tread cracking	
MAJOR	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Nearside Rear tyre cracking	
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
<b>MAJOR</b> 155/65/14	Offside Rear Tyre has a cut in excess of the requirements deep enough to (5.2.3 (d) (i))	reach the ply or cords

MOT #3	2017-07-12 11:38
MOT test number	350790440721
Result	✓ Passed
Advice Nearside Rear Nail in tyre	
MOT #2	2017-07-12 11:38
MOT test number	890862229714
Result	× Failed

 Pass with rectification
 Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

 Advice
 Nearside Rear Nail in tyre

MOT #1	2016-07-13 10:38
MOT test number	173296167347
Result	✓ Passed



Single payment (12 months)

Tax & MOT check

X Untaxed Tax expired: 1 January 2024	<b>X</b> <b>MOT</b> Expired: 3 January 2024
Tax status	Expired at 1 January 2024
Days left	118 days too late
MOT expiry date	3 January 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	А

£0,00,-

Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





# Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
******	
******	
*********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-07-31
Last registration	2022-12-05
Complete history	See info



Registration #1	2013-07-31	27 mi
Registration #2	2016-07-13	27.768 mi
Registration #3	2017-07-12	36.826 mi
Registration #4	2017-07-12	36.826 mi
Registration #5	2018-07-25	46.309 mi
Registration #6	2018-07-25	46.309 mi
Registration #7	2019-06-26	54.821 mi
Registration #8		11.317 esi
Registration #8 Registration #9		11.517 es
-		01.000 est 01.000 est 01.000 est
Registration #9		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		0.000 es
Registration #9 Registration #10 Registration #11		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es





# Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12