



**BD55WGA**

report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Silver
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg






Internet history

Entry 1

Date	2021-06-27
Pictures	21
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2021-02-11 10:25
<b>MOT test number</b>	736529347626
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-02-10
<b>Advice</b>	Exhaust has a minor leak of exhaust gases back box corroded and blowing (6.1.2 (a))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

<b>MOT #15</b>	2019-11-26 09:27
<b>MOT test number</b>	665701584853
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Shock absorbers light misting of oil or has limited damping effect offside and nearside, reduced damping (5.3.2 (b))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #14</b>	2018-12-10 13:50
<b>MOT test number</b>	417841284427
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2018-12-10 10:27
<b>MOT test number</b>	377207709183
<b>Result</b>	✗ Failed
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2017-11-30 09:31**MOT test number** 616911052559**Result** ✓ Passed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Advice** Offside Rear Tyre worn close to the legal limit also perished (4.1.E.1)

**MOT #11** 2017-11-30 09:31**MOT test number** 390552400727**Result** ✗ Failed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Advice** Offside Rear Tyre worn close to the legal limit also perished (4.1.E.1)

**Pass with rectification** Exhaust has a major leak of exhaust gases back box (7.1.2)

**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10** 2016-11-28 08:54**MOT test number** 663028447312**Result** ✓ Passed

**Advice** Nearside Rear Nail in tyre

**Advice** OFFSIDE REAR TYRE PERISHED

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-12-02 10:51**MOT test number** 691584686876**Result** ✓ Passed

**Advice** Offside front tyre wearing on inner wall

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2014-12-01 10:04**MOT test number** 816155034306**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-12-01 10:04**MOT test number** 788365634314**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicators incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Direction indicators incorrect colour (1.4.A.2f)**MOT #6** 2013-12-07 10:45**MOT test number** 235721143352**Result** ✓ Passed**MOT #5** 2012-12-01 12:31**MOT test number** 389656032325**Result** ✓ Passed**MOT #4** 2011-12-03 10:43**MOT test number** 908157031301**Result** ✓ Passed**MOT #3** 2010-12-04 10:42**MOT test number** 803868130324**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #2	2009-11-28 10:46
MOT test number	503992639398
Result	✓ Passed

MOT #1	2008-11-28 11:30
MOT test number	493313538395
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>BD55WGA</b>
Plate since	2024-03-28
Current registration	<b>BD55WGA</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-12-05
Last registration	2021-02-11
Complete history	<a href="#">See info</a>



Registration #1	2005-12-05	26 mi
Registration #2	2008-11-28	21.804 mi
Registration #3	2009-11-28	28.890 mi
Registration #4	2010-12-04	36.888 mi
Registration #5	2011-12-03	43.566 mi
Registration #6	2012-12-01	50.755 mi
Registration #7	2013-12-07	56.208 mi
Registration #8	2014-12-01	61.884 mi
Registration #9	2015-12-02	68.862 mi
Registration #10	2016-12-02	75.840 mi
Registration #11	2017-12-02	82.818 mi
Registration #12	2018-12-02	89.796 mi
Registration #13	2019-12-02	96.774 mi
Registration #14	2020-12-02	103.752 mi
Registration #15	2021-02-11	110.730 mi
Registration #16	2021-02-11	110.730 mi
Registration #17	2021-02-11	110.730 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1082 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	5J13755
---------------	---------