



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO GL
Colour	Silver
Year of manufacture	2004
Top speed	90 mph
0 - 60 mph	15.2 seconds
Gearbox	3 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	85 Nm at 3.200 rpm
Engine capacity	1.061 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2021-01-21
Pictures	13
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-10
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	51
Total items failed	10

MOT #20	2024-01-08 13:31
MOT test number	632038371450
Result	✓ Passed
Next expiry date	2025-01-10
Minor	Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both front (2.1.3 (g) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Rear subframe and coil spring corroded

MOT #19	2022-12-28 11:32
MOT test number	324005461719
Result	✓ Passed

MOT #18	2022-01-08 11:59
MOT test number	700940707732
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #17	2021-01-11 11:54
MOT test number	113165896035
Result	✓ Passed

**MOT #16**

2021-01-08 06:50

MOT test number

407224541535

Result**✗ Failed****Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Exhaust has a major leak of exhaust gases front pipe (6.1.2 (a))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**MOT #15**

2019-05-11 08:25

MOT test number

919808859964

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Coil spring corroded all four (5.3.1 (b) (i))**Advice** Front brakes binding slightly**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

**MOT #14** 2018-05-19 10:24**MOT test number** 473689817298**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Coil spring corroded all springs (2.4.C.1b)**Advice** Off side rear brake binding slightly**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear silencer in poor condition**MOT #13** 2018-05-19 09:31**MOT test number** 491752335632**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Off side rear brake binding slightly**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Coil spring corroded all springs (2.4.C.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear silencer in poor condition**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #12** 2017-05-17 14:21**MOT test number** 469978922727**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2016-05-25 10:57**MOT test number** 282063062607**Result** ✓ Passed**MOT #10** 2015-05-15 15:32**MOT test number** 167615735144**Result** ✓ Passed**Notice** Exhaust back box outter shell coming away**MOT #9** 2015-05-14 15:06**MOT test number** 648284535184**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** Rear wiper blade split**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Exhaust back box outter shell coming away**Fail** Offside Rear Stop lamp not working (1.2.1b)**MOT #8** 2014-06-02 10:08**MOT test number** 107883154168**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Oil leak

**MOT #7** 2013-05-17 10:37**MOT test number** 559467433138**Result** ✓ Passed**Notice** Front brake discs inner faces corroded**Notice** Rear silencer outer skin corroding away**Notice** Rear springs corroded**MOT #6** 2012-05-16 11:05**MOT test number** 305367632115**Result** ✓ Passed**Notice** Front brake discs inner faces corroding**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Rear silencer outer skin corroding away**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2011-05-18 16:00**MOT test number** 268948131194**Result** ✓ Passed**Notice** Front brake discs corroded slightly

**MOT #4** 2010-05-19 12:49**MOT test number** 722029330167**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**Advice** Nearside Front brake disc slightly scored (3.5.1h)**MOT #3** 2009-05-15 15:30**MOT test number** 100155839118**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**MOT #2** 2008-05-24 12:16**MOT test number** 341315448124**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**MOT #1** 2007-02-27 15:13**MOT test number** 141828157407**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front brake disc slightly pitted (3.5.1h)



Tax & MOT check

X

Untaxed

Tax expired:
27 April 2024

✓

MOT

Expires:
10 January 2025

Tax status	Expired at 27 April 2024
Days left	2 days too late
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-02
Last registration	2024-01-08
Complete history	See info



Registration #1	2004-03-02	24 mi
Registration #2	2007-02-27	4.245 mi
Registration #3	2008-05-24	6.059 mi
Registration #4	2009-05-15	8.067 mi
Registration #5	2010-05-19	9.412 mi
Registration #6	2011-05-18	10.247 mi
Registration #7	2012-05-16	12.050 mi
Registration #8	2013-05-17	13.176 mi
Registration #9	2014-06-02	14.725 mi
Registration #10	2015-05-14	15.956 mi
Registration #11	2015-05-15	15.960 mi
Registration #12	2016-05-25	17.536 mi
Registration #13	2016-05-25	17.536 mi
Registration #14	2016-05-25	17.536 mi
Registration #15	2016-05-25	17.536 mi
Registration #16	2016-05-25	17.536 mi
Registration #17	2016-05-25	17.536 mi
Registration #18	2016-05-25	17.536 mi
Registration #19	2016-05-25	17.536 mi
Registration #20	2016-05-25	17.536 mi
Registration #21	2016-05-25	17.536 mi
Registration #22	2016-05-25	17.536 mi
Registration #23	2016-05-25	17.536 mi

More info >



Dimensions & weight

Width	1475 mm
Height	1455 mm
Length	3495 mm
Wheel base	2360 mm
Kerb weight	815 kg
Max. allowed weight	1165 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	F10DN 3162550