



report date: 2024-03-29

General information

Make	KIA
Model	RIO LX
Colour	Silver
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 3

Date	2021-07-04
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-06-26
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-19
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2022-03-15 15:38
MOT test number	703546242159
Result	✓ Passed
Next expiry date	2023-03-31
Advice	Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on edge 175 65 14 (5.2.3 (e))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #20	2022-03-14 17:33
MOT test number	260002814920
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on edge 175 65 14 (5.2.3 (e))
Fail	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #19	2021-04-01 08:57
MOT test number	347613302924
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))



MOT #18	2020-03-25 09:49
MOT test number	589764372968
Result	✓ Passed
MOT #17	2019-03-22 10:28
MOT test number	249204322132
Result	✓ Passed
MOT #16	2018-03-28 09:22
MOT test number	498503780642
Result	✓ Passed
MOT #15	2017-03-23 08:36
MOT test number	630070809810
Result	✓ Passed
MOT #14	2016-03-18 09:10
MOT test number	308909664753
Result	✓ Passed
MOT #13	2015-03-13 09:37
MOT test number	176242175047
Result	✓ Passed
MOT #12	2014-03-26 13:57
MOT test number	225735984009
Result	✓ Passed



MOT #11	2014-03-26 11:10
MOT test number	257225284058
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #10	2013-03-21 12:16
MOT test number	449140383019
Result	✓ Passed
Notice	Advise n/s/r tyre perished advise n/s/f wiperblade slighty split
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #9	2012-03-22 09:22
MOT test number	726102682079
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Play in steering rack inner joint(s)

MOT #8	2011-03-17 09:39
MOT test number	185546871049
Result	✓ Passed
Notice	Advise front brake pads low and discs worn
Advice	Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #7** 2010-03-11 11:23**MOT test number** 103450170438**Result** ✓ Passed**MOT #6** 2009-03-10 13:40**MOT test number** 772789669090**Result** ✓ Passed**MOT #5** 2009-03-10 10:41**MOT test number** 132199869062**Result** ✗ Failed

- Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Fail** Nearside Rear Rear wheel bearing rough when rotated (2.6.1)

MOT #4 2008-03-25 15:56**MOT test number** 933775188083**Result** ✓ Passed**MOT #3** 2007-10-18 17:04**MOT test number** 263151297226**Result** ✓ Passed**MOT #2** 2007-09-21 15:13**MOT test number** 154034267286**Result** ✓ Passed



MOT #1	2006-09-13 09:36
MOT test number	704826956212
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	MF53KYZ
Plate since	2024-03-29
Current registration	MF53KYZ
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-09-30
Last registration	2022-03-15
Complete history	See info



Registration #1	2003-09-30	22 mi
Registration #2	2006-09-13	10.383 mi
Registration #3	2007-09-21	12.652 mi
Registration #4	2007-10-18	12.678 mi
Registration #5	2008-03-25	13.639 mi
Registration #6	2009-03-10	18.720 mi
Registration #7	2009-03-10	18.720 mi
Registration #8	2010-03-11	23.563 mi
Registration #9	2011-03-17	27.723 mi
Registration #10	2012-03-22	31.892 mi
Registration #11	2013-03-21	36.066 mi
Registration #12	2014-03-26	39.233 mi
Registration #13	2014-03-26	39.233 mi
Registration #14	2015-03-22	39.233 mi
Registration #15	2016-03-22	39.233 mi
Registration #16	2017-03-22	39.233 mi
Registration #17	2018-03-22	39.233 mi
Registration #18	2019-03-22	39.233 mi
Registration #19	2020-03-22	39.233 mi
Registration #20	2021-03-22	39.233 mi
Registration #21	2022-03-15	39.233 mi
Registration #22	2022-03-15	39.233 mi
Registration #23	2022-03-15	39.233 mi
Registration #24	2022-03-15	39.233 mi
Registration #25	2022-03-15	39.233 mi



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1680 mm
Height	1420 mm
Length	4240 mm
Wheel base	2410 mm
Kerb weight	1144 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	A3E00 307217