



report date: 2024-03-29

General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-25
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-31
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	38
Total items failed	4

MOT #21	2024-03-12 11:45
MOT test number	250178052996
Result	✓ Passed
Next expiry date	2025-03-31

MOT #20	2023-04-01 09:02
MOT test number	680907097512
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19	2022-03-18 10:27
MOT test number	614515640039
Result	✓ Passed

MOT #18	2022-03-16 11:59
MOT test number	244451708775
Result	✗ Failed
MAJOR	Emissions not tested cats have been removed (8.2.1.2 (d))

**MOT #17**

2021-03-24 16:30

**MOT test number**

484120805444

**Result**

✓ Passed

- Advice** Exhaust noisy (8.1.1 (a))
- Advice** Under trays and covers fitted masking some testable items
- Advice** Brake pipe corroded, covered in grease or other material both fronts (1.1.11 (c))
- Advice** General underside age related surface corrosion

**MOT #16**

2021-03-23 13:26

**MOT test number**

592984464355

**Result**

✗ Failed

- Advice** Under trays and covers fitted masking some testable items
- MAJOR** Exhaust catalytic converter missing where one was fitted as standard (8.2.1.1 (a))
- MAJOR** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- MAJOR** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Advice** General underside age related surface corrosion
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- MAJOR** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (8.1.1 (a))
- Advice** Brake pipe corroded, covered in grease or other material both fronts (1.1.11 (c))
- MAJOR** Nearside Rear Headlamp levelling device inoperative suspension mounted levelling device broken (4.1.5 (a))

**MOT #15**

2020-04-01 13:57

**MOT test number**

558055630825

**Result**

✓ Passed

- Advice** Under trays and engine covers fitted masking some testable items
- Advice** Light general underside age related surface corrosion

**MOT #14** 2020-04-01 09:09**MOT test number** 923633548186**Result** ✗ Failed

**MAJOR** Headlamp levelling device inoperative headlight levelling device on rear suspension broken (4.1.5 (a))

**Advice** Under trays and engine covers fitted masking some testable items

**Advice** Light general underside age related surface corrosion

**MOT #13** 2019-07-05 09:51**MOT test number** 389969790648**Result** ✓ Passed

**Advice** Undertrays Conceal Underbody Components

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))

**Advice** Front Exhaust has a minor leak of exhaust gases Downpipe Flexi Damaged (6.1.2 (a))

**Advice** General Underbody & Component Corrosion

**MOT #12** 2018-08-10 10:59**MOT test number** 849526473437**Result** ✓ Passed

**Advice** Engine covers and under trays fitted

**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-08-10 10:59**MOT test number** 944062569995**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Engine covers and under trays fitted**MOT #10** 2017-08-11 10:57**MOT test number** 170026238063**Result** ✓ Passed**Advice** Offside Front tyre wearing inner edge**Advice** Nearside Front tyre wearing inner edge**MOT #9** 2017-08-11 10:57**MOT test number** 272973729617**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front tyre wearing inner edge**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Nearside Front tyre wearing inner edge**MOT #8** 2016-08-24 08:05**MOT test number** 586806058075**Result** ✓ Passed

**MOT #7** 2016-08-22 16:24**MOT test number** 677567722014**Result** ✗ Failed**Fail** Front brake application uneven (3.7.B.2)**MOT #6** 2016-04-29 11:31**MOT test number** 238178439777**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-04-09 11:11**MOT test number** 177409595009**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2014-04-07 11:10**MOT test number** 609387394018**Result** ✓ Passed**MOT #3** 2013-05-01 15:30**MOT test number** 656551723141**Result** ✓ Passed**MOT #2** 2011-12-28 09:37**MOT test number** 448572261452**Result** ✓ Passed**Notice** Near side rear bumper reflector lens lose



MOT #1	2010-07-02 15:44
MOT test number	280613380412
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
31 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	31 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-27
Last registration	2024-03-12
Complete history	<a href="#">See info</a>



Registration #1	2007-06-27	18 mi
Registration #2	2010-07-02	17.720 mi
Registration #3	2011-12-28	35.244 mi
Registration #4	2013-05-01	47.982 mi
Registration #5	2014-04-07	50.312 mi
Registration #6	2015-04-09	52.418 mi
Registration #7	2016-04-29	54.225 mi
Registration #8	2016-08-22	54.735 mi
Registration #9	2016-08-24	54.735 mi
Registration #10	2017-08-11	58.671 mi
Registration #11	2017-08-11	58.671 mi
Registration #12	2018-08-10	364.043 mi
Registration #13	2019-08-10	364.043 mi
Registration #14	2019-08-10	364.043 mi
Registration #15	2019-08-10	364.043 mi
Registration #16	2019-08-10	364.043 mi
Registration #17	2019-08-10	364.043 mi
Registration #18	2019-08-10	364.043 mi
Registration #19	2019-08-10	364.043 mi
Registration #20	2019-08-10	364.043 mi
Registration #21	2019-08-10	364.043 mi
Registration #22	2019-08-10	364.043 mi
Registration #23	2019-08-10	364.043 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1542 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	577793