





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE SCENIC FIDJI 16V SCENIC
Colour	Red
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J



CarCheck.co.uk page 1/13



report date: 2024-03-28


Internet history

Entry 3

Date 2021-10-25

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-10-18
------	------------

Pictures 12

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date 2021-10-11

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2022-01-10
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	11
Total items failed	10

MOT #22		2021-01-11 13:30
MOT test	number	889940261564
Result		✓ Passed
Next expi	ry date	2022-01-10
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))

MOT #21	2	021-01-11 12:35
MOT test i	number	184706454991
Result		X Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Of	fside Front Headlamp not working on main beam (4.1.1 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #20		2019-11-20 16:52
MOT test	number	894633900448
Result		✓ Passed
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive i	movement (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #19 2019-11-20 16:52

MOT test number 462158859895

Result X Failed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #18 2018-11-23 09:58

MOT test number 461589777307

Result
✓ Passed

MOT #17 2017-10-12 13:28

MOT test number 665264842649

MOT #16 2016-09-02 13:26

MOT test number 958411812647

Result ✓ Passed

MOT #15 2016-09-02 11:29

MOT test number 926111653770

Result X Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #14 2015-09-01 17:11

MOT test number 656544145202

Result ✓ Passed

CarCheck.co.uk page 4/13



Result

MOT #7

Result

Notice

MOT test number

All discs deteriorated

FA52WWH

report date: 2024-03-28

✓ Passed

✓ Passed

2010-08-25 11:50

371777330291

MOT #13	2014-08-20 09:31
MOT test number	375922034467
Result	✓ Passed
MOT #12	2013-08-23 13:19
MOT test number	358275233479
Result	✓ Passed
MOT #11	2013-08-22 11:14
MOT test number	335404033452
Result	× Failed
Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
MOT #10	2013-08-22 10:45
MOT test number	449564633288
Result	✓ Passed
MOT #9	2012-08-23 11:34
MOT test number	505816732267
Result	✓ Passed
	• . 35564
MOT #8	2011-08-25 12:33
MOT test number	798257531209

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6 2009-12-09 10:10

MOT test number 510093249346

Result × Failed

Pass with rectification

Nearside Front suspension has excessive play in a lower suspension ball joint

(2.5.B.1a)

MOT #5 2009-12-09 10:10

MOT test number 481983849453

Result ✓ Passed

MOT #4 2008-10-20 16:25

MOT test number 483074398226

Advice Rear brake disc slightly scored (3.5.1h)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2007-10-16 13:05

MOT test number 483009587246

Result ✓ Passed

MOT #2 2007-10-16 13:05

MOT test number 781369987271

Result X Failed

Pass with rectification Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)

Pass with rectification Registration plate lamp not working (1.1.5c)

MOT #1 2006-10-19 15:00

MOT test number 892462896280

Result

Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Х МОТ

Tax expired: 1 October 2021 Expired: 10 January 2022

Tax status	Expired at 1 October 2021
Days left	941 days too late
MOT expiry date	10 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAUL have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this RENAULT had different number plates.	owner matery		
See in this check if this RENAULT had different number plates.			JLT
See in this check if this RENAULT had different number plates.	HARMAN AND AND AND AND AND AND AND AND AND A		
See in this check if this RENAULT had different number plates.			
See in this check if this RENAULT had different number plates.	***************************************		
See in this check if this RENAULT had different number plates.	********		
See in this check if this RENAULT had different number plates.			
See in this check if this RENAULT had different number plates.	***************************************		
See in this check if this RENAULT had different number plates.		More info >	
以K UK	Plate changes		
Plate since	See in this check if this RENAULT had different number plates.		
Plate since	Number of plates		
	Current registration	UK NEW TOWN	
	Plate since		
	Current registration	NK NY	
Plate since	Plate since		
More info >		More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-11-01
Last registration	2021-01-11
Complete history	See info



Registration #1	2002-11-01	15 mi
Registration #2	2006-10-19	30.208 mi
Registration #3	2007-10-16	37.387 mi
Registration #4	2008-10-20	43.301 mi
Registration #5	2009-12-09	46.332 mi
Registration #6	2010-08-25	48.925 mi
Registration #7	2011-08-25	57.893 mi
Registration #8	2012-08-23	69.550 mi
Registration #9	2013-08-22	79.229 mi
Registration #10	2013-08-22	79.229 mi
Registration #11	2013-08-23	79.270 mi
Registration #12	2014-08-20	90.581 mi
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es

More info >



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1698 mm
Height	1675 mm
Length	4169 mm
Wheel base	2580 mm

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D103463

CarCheck.co.uk page 13/13