





report date: 2024-03-28

## General information

Make	HONDA
Model	JAZZ I-VTEC EX
Colour	Grey
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	101 BHP
Max. torque	123 Nm at 5.000 rpm
Engine capacity	1.318 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28


## Internet history

## Entry 1


Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-26
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	1

MOT #7	2023-10-17 13:51
MOT test number	907041009860
Result	✓ Passed
Next expiry date	2024-10-26

MOT #6	2022-10-27 15:24
MOT test number	582210169514
Result	✓ Passed

MOT #5		2022-04-04 11:50
MOT test	number	482733796988
Result		<b>✓</b> Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



**Advice** 

**NL67VRW** 

report date: 2024-03-28

MOT test number

Result

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number
917619124862

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #2
 2020-09-10 08:51

 MOT test number
 314945434029

 Result
 ✓ Passed

 MOT #1
 2020-09-10 08:51

 MOT test number
 617091372095

 Result
 X Failed

 Pass with rectification
 Offside Front Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	26 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra HONDA salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner h	บระการ

For how long did the current and previous owner(s) have this HONDA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	UK NK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-29
Last registration	2023-10-17
Complete history	See info



Registration #1	2017-09-29	28 mi
Registration #2	2020-09-10	13.036 mi
Registration #3	2020-09-10	13.036 mi
Registration #4		11.777 es
Registration #5	2021-04-14	13.068 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	93%
Children	85%
Pedestrian	73%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1694 mm
Height	1550 mm
Length	3995 mm
Wheel base	2530 mm
Kerb weight	1113 kg
Max. allowed weight	1605 kg

## Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L13B21111261

CarCheck.co.uk page 11/11