



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 D SE LUX
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G








Internet history

Entry 1

Date	2021-06-05
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-27
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	21
Total items failed	7

MOT #19	2024-03-28 14:05
MOT test number	345739686658
Result	✓ Passed
Next expiry date	2025-03-27
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2024-03-21 13:22

MOT test number

672414133359

Result**✗ Failed**

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17

2023-02-14 11:33

MOT test number

826190831581

Result**✓ Passed****MOT #16**

2023-02-13 16:51

MOT test number

159902787932

Result**✗ Failed**

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15

2021-06-09 09:06

MOT test number

973363356270

Result**✓ Passed**

**MOT #14** 2020-07-10 09:46**MOT test number** 360386722548**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear tyres worn on inner edge**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/40/18 (5.2.3 (e))**MOT #13** 2019-07-26 10:40**MOT test number** 609756046058**Result** ✓ Passed**MOT #12** 2018-07-13 08:27**MOT test number** 697676125683**Result** ✓ Passed**MOT #11** 2018-07-13 08:27**MOT test number** 903529591757**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #10** 2017-07-28 16:09**MOT test number** 547120803369**Result** ✓ Passed**MOT #9** 2017-07-28 09:28**MOT test number** 801243309822**Result** ✗ Failed**Fail** Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2017-03-22 17:33**MOT test number** 635615321053**Result** ✓ Passed

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt slight leak of grease (2.5.C.1a)

MOT #7 2017-03-17 13:32**MOT test number** 359492352363**Result** ✗ Failed

Fail Nearside Rear Tyre has ply or cords exposed 235/40/18 (4.1.D.1b)

Advice Offside Rear Tyre worn on inner edge

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt slight leak of grease (2.5.C.1a)

MOT #6 2016-03-26 09:10**MOT test number** 112434613733**Result** ✓ Passed**MOT #5** 2015-03-14 11:42**MOT test number** 226233375041**Result** ✓ Passed**MOT #4** 2014-03-18 12:24**MOT test number** 947677874058**Result** ✓ Passed



MOT #3	2014-03-14 10:05
MOT test number	256283574051
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #2	2013-03-15 10:44
MOT test number	355134973024
Result	✓ Passed
Notice	Front tyres worn on inside edges

MOT #1	2012-03-21 13:31
MOT test number	799141482041
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK09WCG
Plate since	2024-03-28
Current registration	AK09WCG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-27
Last registration	2024-03-28
Complete history	See info



Registration #1	2009-03-27	16 mi
Registration #2	2012-03-21	26.018 mi
Registration #3	2013-03-15	31.570 mi
Registration #4	2014-03-14	37.339 mi
Registration #5	2014-03-18	37.339 mi
Registration #6	2015-03-14	40.059 mi
Registration #7	2016-03-26	42.255 mi
Registration #8	2017-03-17	44.681 mi
Registration #9	2017-03-22	44.681 mi
Registration #10	2017-07-28	45.786 mi
Registration #11	2017-07-28	45.786 mi
Registration #12	2017-07-28	45.786 mi
Registration #13	2017-07-28	45.786 mi
Registration #14	2017-07-28	45.786 mi
Registration #15	2017-07-28	45.786 mi
Registration #16	2017-07-28	45.786 mi
Registration #17	2017-07-28	45.786 mi
Registration #18	2017-07-28	45.786 mi
Registration #19	2017-07-28	45.786 mi
Registration #20	2017-07-28	45.786 mi
Registration #21	2017-07-28	45.786 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1722 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	484941