



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	JETTA GT TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	-
Top speed	137 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg



LABEL UNKNOWN



Internet history

Entry 3

Date	2021-09-17
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2



Date	2021-09-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-08-23
Pictures	24
Listing price	View report



source: [heyicar.co.uk](https://www.heyicar.co.uk)

**MOT history**

MOT #5	2022-10-05 06:39
MOT test number	712507273192
Result	✓ Passed
Next expiry date	2023-10-06
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Slight bind in rear brakes
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2022-10-04 10:13
MOT test number	499042941419
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Slight bind in rear brakes
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #3	2021-10-07 11:13
MOT test number	742675054431
Result	✓ Passed



MOT #2	2021-03-18 11:11
MOT test number	249108049720
Result	✓ Passed

MOT #1	2021-03-17 08:57
MOT test number	641119667720
Result	✗ Failed
<div><div>Fail</div> Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))</div> <div><div>Fail</div> Electronic stability control warning lamp indicates a fault (7.12 (e))</div> <div><div>Advice</div> Nearside Rear Nail in tyre</div> <div><div>Fail</div> Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))</div> <div><div>Fail</div> Electronic power steering warning lamp indicates a system malfunction (2.6 (a))</div>	



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	FY66TWW
Plate since	2019-06-29
Current registration	FY66TWW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-01
Last registration	2022-10-05
Complete history	See info



Registration #1	2016-12-01	20 mi
Registration #2	2021-03-17	35.021 mi
Registration #3	2021-03-18	35.027 mi
Registration #4	2022-05-20	35.277 mi
Registration #5	2022-05-20	35.277 mi
Registration #6	2022-05-20	35.277 mi
Registration #7	2022-05-20	35.277 mi
Registration #8	2022-05-20	35.277 mi
Registration #9	2022-05-20	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	86%
Pedestrian	56%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2020 mm
Height	1482 mm
Length	4755 mm
Wheel base	2651 mm
Kerb weight	1425 kg
Max. allowed weight	1940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CUUB154116