



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Black
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B





MOT history

MOT expiry date	2024-11-17
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	22
Total items failed	9

MOT #16	2023-11-18 15:53
MOT test number	517631351309
Result	✓ Passed
Next expiry date	2024-11-17
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15	2022-10-27 09:02
MOT test number	102267856371
Result	✓ Passed

MOT #14	2021-11-01 13:32
MOT test number	944436270205
Result	✓ Passed

MOT #13	2020-11-05 17:48
MOT test number	793643979896
Result	✓ Passed
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #12**

2019-11-01 11:38

MOT test number

809930150867

Result

✓ Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #11

2019-11-01 11:23

MOT test number

906086322659

Result

✗ Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Fail Brake pedal anti-slip provision missing (1.1.2 (c))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2019-05-10 16:18**MOT test number** 629690857299**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-10-09 12:41**MOT test number** 179635768154**Result** ✓ Passed**MOT #8** 2018-04-12 15:21**MOT test number** 901480921369**Result** ✓ Passed**MOT #7** 2017-11-11 14:18**MOT test number** 429267783523**Result** ✓ Passed**MOT #6** 2017-04-10 12:19**MOT test number** 432963648290**Result** ✓ Passed**MOT #5** 2016-10-13 13:48**MOT test number** 806622216313**Result** ✓ Passed**MOT #4** 2016-04-20 16:18**MOT test number** 836989586938**Result** ✓ Passed



MOT #3	2016-01-18 13:38
MOT test number	583211256698
Result	✓ Passed

MOT #2	2015-01-12 16:06
MOT test number	539782015064
Result	✓ Passed
<div><div>Notice</div>Nearside front indicator damaged</div> <div><div>Notice</div>Brake pedal rubber showing metal</div>	

MOT #1	2015-01-12 12:13
MOT test number	158182615456
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)</div> <div><div>Notice</div>Nearside front indicator damaged</div> <div><div>Fail</div>Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div> <div><div>Fail</div>Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)</div> <div><div>Notice</div>Brake pedal rubber showing metal</div> <div><div>Fail</div>Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)</div> <div><div>Notice</div>Free play in handbrake</div> <div><div>Fail</div>Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div> <div><div>Fail</div>Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 November 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	17 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	YF61UTB
Plate since	2019-09-28
Current registration	YF61UTB
Plate since	2019-09-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-02-09
Last registration	2023-11-18
Complete history	See info



Registration #1	2012-02-09	17 mi
Registration #2	2015-01-12	91.906 mi
Registration #3	2015-01-12	91.906 mi
Registration #4	2016-01-18	123.072 mi
Registration #5	2016-04-20	124.002 mi
Registration #6	2016-10-13	127.214 mi
Registration #7	2017-04-10	129.500 mi
Registration #8	2017-11-11	142.007 mi
Registration #9	2018-04-12	152.402 mi
Registration #10	2019-05-20	161.277 mi
Registration #11	2019-05-20	161.277 mi
Registration #12	2019-05-20	161.277 mi
Registration #13	2019-05-20	161.277 mi
Registration #14	2019-05-20	161.277 mi
Registration #15	2019-05-20	161.277 mi
Registration #16	2019-05-20	161.277 mi
Registration #17	2019-05-20	161.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2023931