





report date: 2024-03-29

#### General information

Make	CITROEN
Model	BERLINGO E-HDI DSTYLE NAV
Colour	White
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-05-25

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	2
Total items failed	10

MOT #9	2023-05-25 10:55
MOT test number	784369426795
Result	✓ Passed
Next expiry date	2024-05-28

MOT #8	2022-05-11 12:44
MOT test number	276161086548
Result	<b>✓</b> Passed

MOT #7	2021-05-29 10:18
MOT test number	363380935888
Result	<b>✓</b> Passed
Minor Offside Front Outer Drive shaft joint constant velocity boo	ot severely deteriorated (6.1.7 (g) (i))

MOT #6	2021-05-28 12:56
MOT test number	159687862046
Result	<b>X</b> Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deterior	ated (6.1.7 (g) (i))
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2020-09-14 16:02

**MOT test number** 201048095823

**MOT #4** 2020-09-14 11:25

**MOT test number** 112471363862

**Result** X Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2019-09-16 16:21

MOT test number 694724683160

Result \( \sqrt{Passed} \)

**MOT #2** 2018-07-25 13:49

**MOT test number** 457697763055

**Result** ✓ Passed

**MOT #1** 2018-07-24 12:40

**MOT test number** 119077835894

**Result** X Failed

Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps BOTH (4.7.1 (b) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

$\sim$	ner	h:-	L
( ) \ \ \	ner	nıs	$\mathbf{r}$

*		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OEN
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-31
Last registration	2023-05-25
Complete history	See info



Registration #1	2015-07-31	16 mi
Registration #2	2018-07-24	104.602 mi
Registration #3	2018-07-25	104.603 mi
Registration #4	2019-09-16	118.478 mi
Registration #5	2020-09-14	124.815 mi
Registration #6	2020-09-14	124.815 mi
Registration #7		D.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.771 44
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1810 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBFV0073337

CarCheck.co.uk page 11/11