



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S (79BHP)
Colour	Black
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	152 g/km
CO2 label	G





MOT history

MOT expiry date	2024-12-10
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	26
Total items failed	16

MOT #19 2023-11-11 09:53

MOT test number 632862238473

Result ✓ Passed

Next expiry date 2024-12-10

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Suspension component corroded but not seriously weakened Arms,Shocks,links (5.3.3 (b) (i))

MOT #18 2022-11-22 15:51

MOT test number 984223630999

Result ✓ Passed

Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

MOT #17 2022-11-15 10:55

MOT test number 336822946416

Result ✗ Failed

Pass with rectification Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**MOT #16** 2021-12-06 16:44**MOT test number** 592384128671**Result** ✓ Passed**MOT #15** 2021-12-06 09:18**MOT test number** 961509849175**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MOT #14** 2020-11-27 17:48**MOT test number** 216215481808**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13**

2020-11-26 12:51

MOT test number

730674691782

Result**✗ Failed****Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Handbrake has high travel**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Power steering inoperative (2.1.5 (c) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Central Exhaust system insecure (6.1.2 (a))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #12**

2019-11-17 13:31

MOT test number

513986800431

Result**✓ Passed****Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2018-12-11 09:59

MOT test number

299947930286

Result

✓ Passed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Front Service brake fluctuating, but not excessively both (1.2.1 (e))
- Advice** Nearside Rear tyre perished
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #10

2017-11-02 14:39

MOT test number

279557778090

Result

✓ Passed

MOT #9

2017-01-05 09:56

MOT test number

221426111200

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Offside Rear tyre cracking but no cords showing

MOT #8

2017-01-04 11:25

MOT test number

192548239638

Result

✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Offside Rear tyre cracking but no cords showing
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #7** 2016-09-07 10:50**MOT test number** 922695065756**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-09-14 11:41**MOT test number** 851335140589**Result** ✓ Passed**MOT #5** 2014-09-15 15:45**MOT test number** 746208254219**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2013-09-24 16:58**MOT test number** 657197063242**Result** ✓ Passed**MOT #3** 2012-02-23 16:21**MOT test number** 966464052017**Result** ✓ Passed**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2010-03-29 16:31**MOT test number** 643018780043**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12010-03-29 16:19

MOT test number324908480062

Result

Failed

- Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail

Offside Front Direction indicators incorrect colour (1.4.A.2f)
- Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-26
Last registration	2023-11-11
Complete history	See info



Registration #1	2007-03-26	20 mi
Registration #2	2010-03-29	15.903 mi
Registration #3	2010-03-29	15.903 mi
Registration #4	2012-02-23	20.865 mi
Registration #5	2013-09-24	23.557 mi
Registration #6	2014-09-15	28.190 mi
Registration #7	2015-09-14	32.248 mi
Registration #8	2016-09-07	36.270 mi
Registration #9	2017-01-04	37.608 mi
Registration #10	2017-01-05	37.608 mi
Registration #11	2017-01-05	37.608 mi
Registration #12	2017-01-05	37.608 mi
Registration #13	2017-01-05	37.608 mi
Registration #14	2017-01-05	37.608 mi
Registration #15	2017-01-05	37.608 mi
Registration #16	2017-01-05	37.608 mi
Registration #17	2017-01-05	37.608 mi
Registration #18	2017-01-05	37.608 mi
Registration #19	2017-01-05	37.608 mi
Registration #20	2017-01-05	37.608 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1191 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BUD 175163