



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SVE
Colour	Silver
Year of manufacture	2005
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-06-30
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-02-27
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	30
Total items failed	12

MOT #22	2022-02-28 14:01
MOT test number	520969084061
Result	✓ Passed
Next expiry date	2023-02-27
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-02-21 15:21
MOT test number	932994455327
Result	✗ Failed
Fail	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #20**

2021-02-11 15:00

**MOT test number**

829748193768

**Result**

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive sump (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 195/55/16 (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

**MOT #19**

2020-02-13 17:29

**MOT test number**

343365200260

**Result**

✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #18**

2020-02-11 14:43

**MOT test number**

523459340692

**Result**

✗ Failed

- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #17**

2019-02-07 14:37

**MOT test number**

322758074288

**Result**

✓ Passed

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #16** 2018-02-09 12:38**MOT test number** 945569245984**Result** ✓ Passed**MOT #15** 2018-02-09 10:39**MOT test number** 300625638308**Result** ✗ Failed

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)

**MOT #14** 2017-02-09 14:01**MOT test number** 971266715295**Result** ✓ Passed**MOT #13** 2017-02-08 09:56**MOT test number** 223852718864**Result** ✗ Failed

**Fail** Nearside Stop lamp not working (1.2.1b)

**Fail** Offside Front brake disc in such a condition that it is seriously weakened on inside (3.5.1i)

**Fail** Nearside Front brake disc in such a condition that it is seriously weakened on inside (3.5.1i)

**MOT #12** 2016-02-16 09:18**MOT test number** 295390422952**Result** ✓ Passed

**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #11** 2016-02-15 11:50**MOT test number** 113785870251**Result** ✗ Failed**Fail** Nearside Front front brake binding (3.7.B.1)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-02-17 14:57**MOT test number** 145568245462**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2014-02-18 14:16**MOT test number** 106589344435**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2013-02-13 11:56**MOT test number** 215324443077**Result** ✓ Passed

**MOT #7** 2013-02-13 11:56**MOT test number** 758334943004**Result** ✗ Failed**Pass with rectification** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**MOT #6** 2012-02-23 12:31**MOT test number** 776064452058**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2011-01-28 12:22**MOT test number** 927618421033**Result** ✓ Passed**MOT #4** 2010-02-15 10:51**MOT test number** 304176240018**Result** ✓ Passed**MOT #3** 2009-02-24 17:43**MOT test number** 172985659082**Result** ✓ Passed**MOT #2** 2008-08-21 11:36**MOT test number** 971814438265**Result** ✓ Passed**Advice** Nearside Inner Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2008-06-02 11:42
MOT test number	292044358485
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Offside front tyre excessively worn on inner edge





Tax & MOT check

X

Untaxed

Tax expired:  
31 October 2022

X

MOT

Expired:  
27 February 2023

Tax status	Expired at 31 October 2022
Days left	545 days too late
MOT expiry date	27 February 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-07-29
Last registration	2022-02-28
Complete history	<a href="#">See info</a>



Registration #1	2005-07-29	21 mi
Registration #2	2008-06-02	24.847 mi
Registration #3	2008-08-21	26.042 mi
Registration #4	2009-02-24	26.050 mi
Registration #5	2010-02-15	39.060 mi
Registration #6	2011-01-28	50.010 mi
Registration #7	2012-02-23	62.609 mi
Registration #8	2013-02-13	71.584 mi
Registration #9	2014-02-18	78.350 mi
Registration #10	2015-02-17	84.692 mi
Registration #11	2016-02-15	88.333 mi
Registration #12	2016-02-16	88.334 mi
Registration #13	2016-02-17	88.335 mi
Registration #14	2016-02-18	88.336 mi
Registration #15	2016-02-19	88.337 mi
Registration #16	2016-02-20	88.338 mi
Registration #17	2016-02-21	88.339 mi
Registration #18	2016-02-22	88.340 mi
Registration #19	2016-02-23	88.341 mi
Registration #20	2016-02-24	88.342 mi
Registration #21	2016-02-25	88.343 mi
Registration #22	2016-02-26	88.344 mi
Registration #23	2016-02-27	88.345 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	322338