





report date: 2024-03-29

General information

Make	NISSAN
Model	MICRA VIBE
Colour	White
Year of manufacture	2017
Top speed	105 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date	2021-03-04
Pictures	1
Listing price	View report



source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-10
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #5	2023-04-24 10:24	
MOT test number	928242885923	
Result	✓ Passed	
Next expiry date	2024-05-10	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))		
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting front bush (5.3.4 (a) (i))	in excessive movement	

MOT #4	2022-04-25 09:03
MOT test number	308428464623
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in front bush (5.3.4 (a) (i))	excessive movement
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #3	2021-05-11 14:39
MOT test number	489479229183
Result	✓ Passed

CarCheck.co.uk page 3/11



(a) (i))

(i))

WR17TWY
report date: 2024-03-29

MOT #2 2020-07-06 14:42

MOT test number 522723142417

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-07-06 11:02

MOT test number 556591294121

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

o micr motory	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-03-30
Last registration	2023-04-24
Complete history	See info



Registration #1	2017-03-30	8 mi
Registration #2	2020-07-06	30.858 mi
Registration #3	2020-07-06	30.858 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

The NISSAN factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle $\underline{\text{here}}.$

More info >

Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1535 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2
Engine number 878061C