





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TSI DSG
Colour	Grey
Year of manufacture	2019
Top speed	116 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	70 kW / 95 HP / 94 BHP
Max. torque	175 Nm at 2.000 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-05-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT	history
1.101	iliocol y

MOT expiry date	2025-03-13
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #4		2024-03-14 14:46
MOT test	number	959261089793
Result		✓ Passed
Next expi	ry date	2025-03-13
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Lower Undertray Fitted Not Allowing Full Inspection of Some Components	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Central Front Upper Items removed from driver's view prior to test Air Freshener	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



Result

Result

GH19KLL report date: 2024-03-28

X Failed

✓ Passed

MOT #3 2024-03-14 14:46

MOT test number 870904164845

Advice Central Front Upper Items removed from driver's view prior to test Air Freshener

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Lower Undertray Fitted Not Allowing Full Inspection of Some Components

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Front Headlamp aim too low Both Sides (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2023-03-31 10:46

MOT test number 970791360538

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))

Advice Front Lower Undertray Fitted not allowing full inspection of some components.

MOT #1 2022-04-29 14:56

MOT test number 657509917843

037303317013

Advice Front Lower Undertray Fitted Not Allowing Full Inspection of Some Components.

CarCheck.co.uk page 4/11



Tax & MOT check





Tax status	Expired at 14 March 2024
Days left	46 days too late
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



GH19KLL

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-07-27
Last registration	2024-03-14
Complete history	See info



Registration #1	2019-07-27	25 mi
Registration #2	2022-04-29	24.455 mi
Registration #3		11.777 mi
Registration #4		71.777 es
Registration #5		11,777 es
Registration #6		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	85%
Pedestrian	76%
Safety systems	59%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1946 mm
Height	1461 mm
Length	4053 mm
Wheel base	2548 mm
Kerb weight	1080 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	DKLA037561