



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S
Colour	Silver
Year of manufacture	2003
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	170 Nm at 4.000 rpm
Engine capacity	1.783 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-05-14
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	25
Total items failed	18

MOT #27	2023-10-25 06:48
MOT test number	380244565683
Result	✓ Passed
Next expiry date	2024-10-24

MOT #26	2022-09-23 12:52
MOT test number	946126460990
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (1.1.14 (a) (ii))

MOT #25	2021-10-21 16:06
MOT test number	235526945070
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #24** 2020-10-22 16:11**MOT test number** 256801398219**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #23** 2020-10-21 14:30**MOT test number** 451626739313**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #22** 2019-06-10 13:37**MOT test number** 213127301831**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #21** 2019-06-10 10:09**MOT test number** 759375071954**Result** ✗ Failed**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20** 2018-06-11 14:55**MOT test number** 553529703601**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2017-06-09 14:03**MOT test number** 255918111197**Result** ✓ Passed**Advice** Nearside front tyre wearing on inner/outer edge**MOT #18** 2017-06-09 10:34**MOT test number** 520810660761**Result** ✗ Failed**Fail** Offside Headlamp aim too far to the right (1.8)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp aim too far to the right (1.8)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #17** 2016-06-08 10:08**MOT test number** 189459260888**Result** ✓ Passed**Advice** Nearside Front wearing on inside edge

**MOT #16** 2016-06-08 09:28**MOT test number** 175891941654**Result** ✗ Failed**Fail** Body insecure and dangerous to other road users (6.1.B.1b)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Battery insecure (1.9.1)**MOT #15** 2015-06-03 15:29**MOT test number** 949364555125**Result** ✓ Passed**MOT #14** 2015-06-03 15:29**MOT test number** 257024655163**Result** ✗ Failed**Pass with rectification** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #13** 2014-05-15 09:56**MOT test number** 437985034122**Result** ✓ Passed**MOT #12** 2013-06-10 14:28**MOT test number** 218511163109**Result** ✓ Passed

**MOT #11** 2013-06-10 13:15**MOT test number** 996861563120**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage severely distorted (2.4.G.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Anti-roll bar linkage severely distorted (2.4.G.1)**MOT #10** 2012-06-08 18:06**MOT test number** 768130362138**Result** ✓ Passed**MOT #9** 2012-06-08 18:06**MOT test number** 496530462171**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #8** 2011-06-03 17:24**MOT test number** 675394651163**Result** ✓ Passed

**MOT #7** 2011-06-03 11:44**MOT test number** 219504251102**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)

MOT #6 2010-05-27 09:46**MOT test number** 472767640180**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)
- Pass with rectification** Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)

MOT #5 2010-05-27 09:46**MOT test number** 263017240140**Result** ✓ Passed

- Advice** Nearside Rear brake disc slightly pitted (3.5.1h)
- Advice** Nearside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

MOT #4 2009-06-06 11:45**MOT test number** 934777459186**Result** ✓ Passed



MOT #3	2008-05-23 17:02
MOT test number	264784448425
Result	✓ Passed
MOT #2	2007-06-11 17:38
MOT test number	603142567116
Result	✓ Passed
MOT #1	2006-05-27 15:10
MOT test number	750497446183
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-03-17
Last registration	2023-10-25
Complete history	See info



Registration #1	2003-03-17	18 mi
Registration #2	2006-05-27	30.375 mi
Registration #3	2007-06-11	39.541 mi
Registration #4	2008-05-23	48.499 mi
Registration #5	2009-06-06	58.714 mi
Registration #6	2010-05-27	67.131 mi
Registration #7	2011-06-03	73.852 mi
Registration #8	2011-06-03	73.852 mi
Registration #9	2012-06-08	78.778 mi
Registration #10	2013-06-10	82.440 mi
Registration #11	2013-06-10	82.440 mi
Registration #12	2014-05-15	85.713 mi
Registration #13	2015-06-03	87.337 mi
Registration #14	2016-06-03	88.337 mi
Registration #15	2017-06-03	89.337 mi
Registration #16	2018-06-03	90.337 mi
Registration #17	2019-06-03	91.337 mi
Registration #18	2020-06-03	92.337 mi
Registration #19	2021-06-03	93.337 mi
Registration #20	2022-06-03	94.337 mi
Registration #21	2023-06-03	95.337 mi
Registration #22	2024-06-03	96.337 mi
Registration #23	2025-06-03	97.337 mi
Registration #24	2026-06-03	98.337 mi
Registration #25	2027-06-03	99.337 mi
Registration #26	2028-06-03	100.337 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1422 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1255 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Engine number	B4183154400