




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	2005
Top speed	113 mph
0 - 60 mph	12.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	38.7 mpg
Consumption combined	29.4 mpg
CO2 emission	226 g/km
CO2 label	L






Internet history

Entry 2

Date	2021-07-20
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-19
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-15
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	32
Total items failed	3

MOT #22 2023-09-11 11:31

MOT test number 442975718937

Result ✓ Passed

Next expiry date 2024-09-15

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21 2022-08-24 10:03

MOT test number 849491315239

Result ✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #20 2021-08-27 14:34

MOT test number 371579725138

Result ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #19**

2021-08-21 09:54

MOT test number

123052874477

Result**✗ Failed****Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR

Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

MAJOR

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR

Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

MOT #18

2020-09-16 07:24

MOT test number

124760898326

Result**✓ Passed****MOT #17**

2020-09-15 14:19

MOT test number

623085282596

Result**✗ Failed****MAJOR**

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2019-06-13 15:33

MOT test number

156942916425

Result**✓ Passed**

**MOT #15** 2019-06-11 10:37**MOT test number** 413143477941**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Central Rear Exhaust system insecure (6.1.2 (a))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #14** 2018-06-28 11:33**MOT test number** 593944959319**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2017-06-26 10:19**MOT test number** 707552154273**Result** ✓ Passed**MOT #12** 2016-07-02 12:09**MOT test number** 358207344899**Result** ✓ Passed**MOT #11** 2015-07-06 11:16**MOT test number** 309967685193**Result** ✓ Passed**MOT #10** 2014-06-24 10:17**MOT test number** 348695274185**Result** ✓ Passed

**MOT #9** 2013-06-20 09:55**MOT test number** 258361873489**Result** ✓ Passed**MOT #8** 2013-06-20 09:55**MOT test number** 705881273197**Result** ✗ Failed**Pass with rectification** Centre Exhaust system not adequately supported (7.1.1)**MOT #7** 2012-06-13 09:29**MOT test number** 989545062192**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2011-06-22 09:56**MOT test number** 128103771183**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-06-19 12:24**MOT test number** 653880170192**Result** ✓ Passed

**MOT #4** 2009-07-01 12:11**MOT test number** 212552689417**Result** ✓ Passed**MOT #3** 2009-04-17 15:39**MOT test number** 100797509127**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-04-16 16:00**MOT test number** 464106609101**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #1** 2008-01-21 11:53**MOT test number** 930971028014**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
15 September 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-01-24
Last registration	2023-09-11
Complete history	See info



Registration #1	2005-01-24	13 mi
Registration #2	2008-01-21	8.786 mi
Registration #3	2009-04-16	19.153 mi
Registration #4	2009-04-17	19.153 mi
Registration #5	2009-07-01	20.280 mi
Registration #6	2010-06-19	24.575 mi
Registration #7	2011-06-22	28.473 mi
Registration #8	2012-06-13	31.941 mi
Registration #9	2013-06-20	35.581 mi
Registration #10	2014-06-24	38.094 mi
Registration #11	2015-07-06	41.066 mi
Registration #12	2016-07-02	43.927 mi
Registration #13	2016-07-02	43.927 mi
Registration #14	2016-07-02	43.927 mi
Registration #15	2016-07-02	43.927 mi
Registration #16	2016-07-02	43.927 mi
Registration #17	2016-07-02	43.927 mi
Registration #18	2016-07-02	43.927 mi
Registration #19	2016-07-02	43.927 mi
Registration #20	2016-07-02	43.927 mi
Registration #21	2016-07-02	43.927 mi
Registration #22	2016-07-02	43.927 mi
Registration #23	2016-07-02	43.927 mi
Registration #24	2016-07-02	43.927 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1321 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ 737240