





report date: 2024-03-29

General information

Make	MERCEDES
Model	CLS CLS350
Colour	Gold
Year of manufacture	2005
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	272 BHP
Max. torque	350 Nm at 2.400 rpm
Engine capacity	3.498 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.0 mpg
CO2 emission	241 g/km
CO2 label	L



CarCheck.co.uk page 1/15



Internet history

Entry 2

Date 2021-09-12

Pictures 45

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date	2021-09-12
Pictures	45

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2023-12-21
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	27
Total items failed	13

MOT #22		2022-12-22 13:35
MOT test	number	289296470913
Result		✓ Passed
Next expi	ry date	2023-12-21
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Suspension component corroded but not seriously weakened front + rear corroded (5.3.3 (b) (i))	
Advice	Advice Undercover fitted obscuring some components	
Advice cor roded	Advice Integral body structure is corroded but structural rigidity is not significantly reduced undre bonnet cor roded (6.1.1 (c) (i))	

MOT #21	2022-12-22 12:45	
MOT test number	649866286357	
Result	X Failed	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Suspension component corroded but not seriously weakened front + rear corroded (5.3.3 (b) (i))		
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Integral body structure is corroded but structural rigidity is not significantly reduced undre bonnet cor roded (6.1.1 (c) (i))		
Advice Undercover fitted obscuring some components		

CarCheck.co.uk page 3/15



MOT #20 2021-09-11 10:46

MOT test number 301093892629

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2021-09-10 17:00

MOT test number 820530938877

Result X Failed

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2020-12-16 11:53

MOT test number 992919871229

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #17 2019-12-21 15:12

MOT test number 472903654484

Result
✓ Passed

MOT #16 2019-01-10 14:48

MOT test number 584744665816

Result

Passed

CarCheck.co.uk page 4/15



MOT #15 2018-01-31 14:55

MOT test number 658265759892

Result \rightarrow Passed

Advice Brake pipe slightly corroded All (3.6.B.2c)

MOT #14 2017-02-13 14:10

MOT test number 493996761132

MOT #13 2016-03-08 12:29

MOT test number 569405367762

MOT #12 2016-03-07 10:26

MOT test number 974887651379

Result × Failed

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Nearside Front Suspension arm has excessive play in a ball joint suspension arm ball joint worn (2.4.G.2)

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #11 2015-03-16 12:28

MOT test number 766865475093

Advice Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #10 2015-03-14 13:01

MOT test number 439343775007

Result X Failed

Fail Offside rear brake binding (3.7.B.1)

Advice Front Brake pipe slightly corroded (3.6.B.2c)

MOT #9 2014-09-24 14:56

MOT test number 978017564274

Result ✓ Passed

MOT #8 2014-09-24 13:07

MOT test number 979617464283

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Front brake fluctuating, but not excessively (3.7.B.3)

Advice Front Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2013-05-07 11:05

MOT test number 688297823117

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2012-06-01 14:52

MOT test number 827263052153

Result
✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #5 2012-05-29 14:08 578790952149 **MOT** test number Result × Failed Fail Rear Shock absorber has a serious fluid leak (2.7.3) Fail Rear Exhaust system not adequately supported (7.1.1) **Advice** Front Brake pipe slightly corroded (3.6.B.2c) Notice All discs surface rust Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3) Fail Rear Shock absorber has negligible damping effect (2.7.5) Fail Nearside Rear brake caliper securing device missing (3.5.1j)

 MOT #4
 2010-10-19 08:15

 MOT test number
 124532190269

 Result
 ✓ Passed

MOT test number

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Notice O/s front wheel should be on n/s rear and visa versa

MOT #2

MOT test number

Front tyres wearing on edges

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/15



report date: 2024-03-29

 MOT #1
 2008-08-06 09:27

 MOT test number
 611989118220

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check

Tax expired: 30 June 2023



X MOT

Expired: 21 December 2023

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 30 June 2023

305 days too late

21 December 2023

See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

2000000	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-07-14
Last registration	2022-12-22
Complete history	See info



Registration #1	2005-07-14	26 mi
Registration #2	2008-08-06	35.085 mi
Registration #3	2009-08-05	40.387 mi
Registration #4	2010-10-15	47.815 mi
Registration #5	2010-10-19	47.815 mi
Registration #6	2012-05-29	47.951 mi
Registration #7	2012-06-01	47.951 mi
Registration #8	2013-05-07	54.298 mi
Registration #9	2014-09-24	58.195 mi
Registration #10	2014-09-24	58.195 mi
Registration #11	2015-03-14	60.290 mi
Registration #12	2015-03-16	60.290 mi
Registration #13	2016-03-07	64.727 mi
Registration #14		71.777 es
Registration #15		11.177 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
_		



Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1730 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	27296430120574

CarCheck.co.uk page 15/15