



 **WN6IYAA**

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	White
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-11
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	8
Total items failed	8

MOT #12	2024-02-12 16:19
MOT test number	290424959576
Result	✓ Passed
Next expiry date	2025-02-11

MOT #11	2024-02-06 08:58
MOT test number	637712403162

Result	✗ Failed
--------	----------

- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10	2022-12-14 16:03
MOT test number	572139851711

Result	✓ Passed
--------	----------

**MOT #9** 2021-11-11 17:35**MOT test number** 619637669555**Result** ✓ Passed**MOT #8** 2020-09-29 10:31**MOT test number** 118128665312**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2019-10-09 08:59**MOT test number** 555547065598**Result** ✓ Passed**MOT #6** 2019-10-09 08:59**MOT test number** 538610248306**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour bulb faded (4.4.3 (a))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))**Pass with rectification** Offside Rear Direction indicator incorrect colour bulb faded (4.4.3 (a))**MOT #5** 2018-10-10 09:48**MOT test number** 760808758803**Result** ✓ Passed**MOT #4** 2017-10-12 10:09**MOT test number** 853244582928**Result** ✓ Passed

**MOT #3** 2016-10-05 08:59**MOT test number** 578229891962**Result** ✓ Passed**Advice** Both rear tyres are cracked/perishing!**MOT #2** 2015-09-29 08:32**MOT test number** 343522453672**Result** ✓ Passed**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #1** 2014-09-23 10:57**MOT test number** 318796564289**Result** ✓ Passed**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
11 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	WN61YAA
Plate since	2019-09-29
Current registration	WN61YAA
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-10-14
Last registration	2024-02-12
Complete history	See info



Registration #1	2011-10-14	8 mi
Registration #2	2014-09-23	7.288 mi
Registration #3	2015-09-29	9.523 mi
Registration #4	2016-10-05	11.698 mi
Registration #5	2017-10-12	13.858 mi
Registration #6	2018-10-10	15.908 mi
Registration #7	2019-10-09	18.064 mi
Registration #8	2020-09-29	20.217 mi
Registration #9	2021-09-29	22.370 mi
Registration #10	2022-09-29	24.523 mi
Registration #11	2023-09-29	26.676 mi
Registration #12	2024-02-12	28.829 mi
Registration #13	2024-02-12	28.829 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225