





report date: 2024-03-28

General information

Make	VAUXHALL
Model	CORSA SRI NAV
Colour	Red
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	89 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



LD68FPL

report date: 2024-03-28


Internet history

Entry 2

Da	te	2022-01-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-01-05
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-17
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	22
Total items failed	2

MOT #5		2024-01-15 16:33
MOT test	number	776915140563
Result		✓ Passed
Next expi	ry date	2025-01-17
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Nail in tyre	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Advice	Spare tyre defective	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #4 2024-01-13 15:14

MOT test number 625787947261

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Spare tyre defective

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #3 2023-01-16 15:21

MOT test number 526030399612

Result ✓ Passed

MOT #2 2022-01-18 15:12

MOT test number 573229578624

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2021-09-28 13:59

MOT test number 514254770384

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

2000000	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-10-31
Last registration	2024-01-15
Complete history	See info



Registration #1	2018-10-31	17 mi
Registration #2	2021-09-28	27.873 mi
Registration #3		91.777 esi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71,777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	***
Adult	79%
Children	77%
Pedestrian	71%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1746 mm
Height	1481 mm
Length	4021 mm
Wheel base	2510 mm
Kerb weight	1158 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19UC1512LDD

CarCheck.co.uk page 12/12