

\$ SUZUKI



General information

Make	SUZUKI
Model	VITARA SZ-T
Colour	White
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D







LAWSON MOTOR COMPANY

Internet history

Entry 1	
Date	2021-05-26
Pictures	44
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #9	2023-07-10 16:23
MOT test number	244856839762
Result	✓ Passed
Next expiry date	2024-07-09
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #8 2023-07-10 15:31 MOT test number 456955754994 Result X Failed Advice Nearside Front Play in steering rack inner joint(s) Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7	2022-06-07 10:26
MOT test number	257368937608
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #6	2022-06-07 10:26
MOT test number	551435418352
Result	× Failed
Pass with rectification (3.4 (b) (ii))	Nearside Windscreen wiper does not clear the windscreen effectively replaced
Pass with rectification (3.4 (b) (ii))	Offside Windscreen wiper does not clear the windscreen effectively replaced
Minor Windscreen dam	aged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5	2021-06-02 12:00
MOT test number	435545893583
Result	✓ Passed

MOT #4	2021-06-01 12:51
MOT test number	175927226148
Result	🗙 Failed
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to real 215/55/17 (5.2.3 (d) (i))	ach the ply or cords
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2020-06-09 10:03
MOT test	number 557649743419
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.7mm tread depth (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.7mm tread depth (5.2.3 (e))

MOT #2	2019-05-15 15:19
MOT test number	972999056107
Result	✓ Passed





MOT #1	2018-05-17 14:14
MOT test number	936768691476
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 June 2024	Expires: 9 July 2024
Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plat	es.
Number of plates	9
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-23
Last registration	2023-07-10
Complete history	See info



Registration #1	2015-05-23	18 mi
Registration #2	2018-05-17	17.517 mi
Registration #3	2019-05-15	22.630 mi
Registration #4	2020-06-09	26.841 mi
Registration #5		11.777 mi
Registration #6	2021-06-01	29.491 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1150 kg
Max. allowed weight	1730 kg
Additional information	
Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
	5
Engine number	M16A-1929392