





General information

| Make | PEUGEOT |
|---------------------|---------------------|
| Model | 2008 ALLURE PREMIUM |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 104 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 82 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.199 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |








Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-10-09 |
| Pictures | 15 |
| Listing price | View report |









source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-10-11 |
|--------------------|------------|
| MOT pass rate | 50 % |
| MOT passed | 3 |
| Failed MOT tests | 3 |
| Total advice items | 9 |
| Total items failed | 5 |

| MOT #6 | 2023-10-12 10:45 |
|------------------|------------------|
| MOT test number | 775186520780 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-11 |

| MOT #5 | 2023-10-12 10:45 |
|-------------------------|--|
| MOT test number | 394034968228 |
| Result | × Failed |
| Pass with rectification | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Pass with rectification | Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) |

| MOT #4 | 2022-10-11 16:29 |
|--|------------------|
| MOT test number | 225622236561 |
| Result | ✓ Passed |
| Advice Nearside Rear Nail in tyre | |
| Advice Both fronts worn edges | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice TPMS on | |





| МОТ #3 | | 2022-10-11 11:41 |
|-----------------------------------|--|-----------------------|
| MOT test number | | 235877725899 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Front Headlamp not working on dipped | beam (4.1.1 (a) (ii)) |
| Advice Offside Front Ty | re worn close to legal limit/worn on edge (5.2.3 (e) |) |
| Advice Both fronts worr | n edges | |
| Advice Nearside Rear Nail in tyre | | |
| DANGEROUS Nearside | Front Tyre tread depth below requirements of 1.6r | nm (5.2.3 (e)) |
| Advice TPMS on | | |

| MOT #2 | 2021-08-31 13:05 |
|-----------------|------------------|
| MOT test number | 968816089292 |
| Result | ✓ Passed |

| MOT #1 | 2021-08-31 13:05 | |
|---|---|--|
| MOT test number | 422386746150 | |
| Result | × Failed | |
| Pass with rectification all lamps (4.7.1 (b) (ii)) | Offside Rear Registration plate lamp inoperative in the case of a single lamp or | |
| Pass with rectification all lamps (4.7.1 (b) (ii)) | Nearside Rear Registration plate lamp inoperative in the case of a single lamp or | |



Tax & MOT check

| Tax due: 1 November 2024 | MOT Expires: 11 October 2024 |
|------------------------------|------------------------------------|
| Tax status | Valid until 1 November |
| Days left MOT expiry date | 185 11 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---|-------|
| Date | | |
| Category | | ARMP |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | AT I |
| Date | | * |
| Category | AMA | |
| Туре | No. Contraction of the second s | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-09-19 |
| Last registration | 2023-10-12 |
| Complete history | See info |



| Registration #1 | 2018-09-19 | 9 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-08-31 | 39.531 mi |
| Registration #3 | 2021-08-31 | 39.531 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.117 esi |





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 77% |
| Pedestrian | 72% |
| Safety systems | 70% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1829 mm |
| Height | 1556 mm |
| Length | 4159 mm |
| Wheel base | 2538 mm |
| Kerb weight | 1045 kg |
| Max. allowed weight | 1580 kg |
| Additional information | |
| Fuel tank capacity | 50 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | XVA70111485 |