



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-07
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	11

MOT #17 2024-04-08 10:55

MOT test number 686792971766

Result ✓ Passed

Next expiry date 2025-04-07

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #16 2022-12-15 14:34

MOT test number 380986241216

Result ✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15 2022-01-13 08:44

MOT test number 362042706570

Result ✓ Passed

- Advice** Centre exhaust hanger broken

**MOT #14**

2021-06-25 08:57

MOT test number

709519404674

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13

2020-07-16 11:19

MOT test number

750941206622

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wear on inside edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wear on inside edge (5.2.3 (e))

**MOT #12**

2020-07-10 13:49

MOT test number

418492760955

Result

✗ Failed

Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Exhaust mounting defective Middle section mount broken (6.1.2 (a))**Advice** Tyre worn close to legal limit/worn on edge Both front tyres low tread (5.2.3 (e))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))**Advice** Driver's door check strap loose**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front discs pitted and corroded slightly (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11**

2019-06-11 16:00

MOT test number

789734388593

Result

✓ Passed

MOT #10

2018-07-10 11:45

MOT test number

844999748402

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2017-05-31 15:02**MOT test number** 212691190845**Result** ✓ Passed**MOT #8** 2017-05-29 09:21**MOT test number** 624911739864**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #7** 2016-06-08 14:29**MOT test number** 818916879164**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-06-04 10:40**MOT test number** 466895655141**Result** ✓ Passed**MOT #5** 2014-06-04 11:02**MOT test number** 646145954132**Result** ✓ Passed



MOT #4	2014-06-03 15:59
MOT test number	298604754113
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3	2013-06-04 13:44
MOT test number	108355353131
Result	✓ Passed

MOT #2	2012-05-22 10:25
MOT test number	867153242156
Result	✓ Passed

MOT #1	2012-05-22 10:25
MOT test number	266343142445
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
7 April 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-05-14
Last registration	2024-04-08
Complete history	See info



Registration #1	2009-05-14	20 mi
Registration #2	2012-05-22	22.521 mi
Registration #3	2013-06-04	33.204 mi
Registration #4	2014-06-03	45.366 mi
Registration #5	2014-06-04	45.366 mi
Registration #6	2015-06-04	58.660 mi
Registration #7	2016-06-08	64.536 mi
Registration #8	2017-05-29	67.786 mi
Registration #9	2017-05-31	67.796 mi
Registration #10	2018-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2020-05-29	75.277 mi
Registration #13	2021-05-29	75.277 mi
Registration #14	2022-05-29	75.277 mi
Registration #15	2023-05-29	75.277 mi
Registration #16	2024-05-29	75.277 mi
Registration #17	2025-05-29	75.277 mi
Registration #18	2026-05-29	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	613349
---------------	--------