



TOYOTA



M7SHR


report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D VX
Colour	Blue
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2021-11-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	52
Total items failed	3

MOT #192020-10-21 12:01

MOT test number561653465685

Result✓ Passed

Next expiry date2021-11-06

- AdviceO/S/R and N/S/R lower suspension arm inner bushes perishing and splitting
- AdviceOil leak from transfer box
- AdviceRear diff mount split
- AdviceCentre brake pipes corroding
- AdviceRear brake discs corroding
- AdviceOil leak from engine
- AdviceOil lamp on
- AdviceN/S/R child seat fitted
- AdviceMiddle to rear exhaust section corroding & slight blow
- AdviceMetal brake corroding

**MOT #18**

2020-10-20 16:58

**MOT test number**

623405437442

**Result****✗ Failed**

- Advice** Rear brake discs corroding
- Advice** Oil leak from engine
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Oil lamp on
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** N/S/R child seat fitted
- Advice** Metal brake corroding
- Advice** O/S/R and N/S/R lower suspension arm inner bushes perishing and splitting
- Advice** Oil leak from transfer box
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Centre brake pipes corroding

**MOT #17**

2019-11-07 11:03

**MOT test number**

395341183681

**Result****✓ Passed**

- Advice** Oil leak from engine/gearbox
- Advice** Rear diff mountings(x3) worn and split
- Advice** O/s and n/s rear tyres perishing

**MOT #16** 2019-11-06 14:49**MOT test number** 978149680178**Result** ✗ Failed**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** O/s and n/s rear tyres perishing**Advice** Headlamps tarnishing**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak from engine/gearbox**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear diff mountings(x3) worn and split**MOT #15** 2018-10-26 14:36**MOT test number** 818207611464**Result** ✓ Passed**MOT #14** 2017-10-28 11:09**MOT test number** 441431520392**Result** ✓ Passed**MOT #13** 2015-11-10 10:33**MOT test number** 184630340799**Result** ✓ Passed**MOT #12** 2015-03-04 12:31**MOT test number** 628383065049**Result** ✓ Passed

**MOT #11** 2014-02-19 11:42**MOT test number** 549560454006**Result** ✓ Passed**MOT #10** 2013-02-20 11:45**MOT test number** 985621853018**Result** ✓ Passed**MOT #9** 2012-02-22 11:33**MOT test number** 116183052036**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2011-03-09 16:35**MOT test number** 699168361098**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2011-03-09 09:13**MOT test number** 416958661075**Result** ✗ Failed**Advice** Nearside Front front brake grabbing slightly (3.7.A.2b)**Fail** Rear Rear fog lamp not working (1.3.2b)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #6** 2010-05-06 11:29**MOT test number** 230416520108**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-05-06 11:29**MOT test number** 580466120130**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-05-11 11:37**MOT test number** 211881239409**Result** ✓ Passed**MOT #3** 2009-05-11 11:37**MOT test number** 991181739194**Result** ✗ Failed**Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)



MOT #2

2008-04-22 10:36

MOT test number

733353018195

Result

✓ Passed

- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1

2007-01-10 16:09

MOT test number

734240617026

Result

✓ Passed

- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)





Tax & MOT check

✕  
**Untaxed**

**Tax expired:**  
16 January 2021

✕  
**MOT**

**Expired:**  
6 November 2021

<b>Tax status</b>	Expired at 16 January 2021
<b>Days left</b>	1199 days too late
<b>MOT expiry date</b>	6 November 2021
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2002-04-15
Last registration	2020-10-21
Complete history	<a href="#">See info</a>



Registration #1	2002-04-15	11 mi
Registration #2	2007-01-10	66.672 mi
Registration #3	2008-04-22	73.525 mi
Registration #4	2009-05-11	78.387 mi
Registration #5	2010-05-06	81.428 mi
Registration #6	2011-03-09	83.112 mi
Registration #7	2011-03-09	83.112 mi
Registration #8	2012-02-22	86.786 mi
Registration #9	2013-02-20	90.510 mi
Registration #10	2014-02-19	95.064 mi
Registration #11	2015-02-20	95.064 mi
Registration #12	2016-02-20	95.064 mi
Registration #13	2017-02-20	95.064 mi
Registration #14	2018-02-20	95.064 mi
Registration #15	2019-02-20	95.064 mi
Registration #16	2020-02-20	95.064 mi
Registration #17	2021-02-20	95.064 mi
Registration #18	2022-02-20	95.064 mi
Registration #19	2023-02-20	95.064 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	NOT KNOWN